

## Structures in the Municipality of Falmouth

				CONDITION RATINGS	
<b>TOWN1:</b>	Falmouth	<b>TOWN2</b>	Portland	<b>SUBSTRUCTURE CONDITION</b>	6 Satisfactory
<b>BRIDGE NO.:</b>	0277	<b>MAINT REGION</b>	Southern	<b>SUPERSTRUCTURE CONDITION</b>	4 Poor
<b>LOCATION:</b>	51.8 MILE POINT	<b>YEAR BUILT</b>	1955	<b>DECK CONDITION</b>	6 Satisfactory
<b>BRIDGE NAME</b>	PRESUMPCOT RIVER N	<b>SPAN MATERIAL</b>	1 Steel	<b>CHANNEL CONDITION:</b>	7 Good
<b>OWNER:</b>	8 ME TPK	<b>SPAN TYPE:</b>	1 Girder	<b>CULVERT CONDITION:</b>	N Not Applicable
<b>MAINTAINER</b>	8 ME TPK	<b>NUMBER OF MAIN SPANS:</b>	2	<b>APPROACH CONDITION:</b>	
<b>FEATURE ON:</b>	MTPK NB	<b>STRUCTURE LENGTH IN FEET</b>	165	<b>DATE OF INSPECTION:</b>	5/18/2008
<b>FEATURE UNDER</b>	PRESUMPCOT RIVER			<b>FEDERAL SUFFICIENCY RATING</b>	55.2
<b>ROAD INV NO:</b>	000000095X	<b>POSTING STATUS:</b>	1 Open		
<b>ROUTE NO:</b>	95	<b>POSTING TYPE:</b>	0 None needed		
<b>ROAD WIDTH</b>	42				
	<b>FEET</b>				
<b>CLASS:</b>	MAINE TURNPIKE AUTHORITY	<b>FEDERAL BRIDGE INDICATOR:</b>	Y		

## Structures in the Municipality of Falmouth

				CONDITION RATINGS	
<b>TOWN1:</b>	Falmouth	<b>TOWN2</b>	Portland	<b>SUBSTRUCTURE CONDITION</b>	6 Satisfactory
<b>BRIDGE NO.:</b>	1489	<b>MAINT REGION</b>	Southern	<b>SUPERSTRUCTURE CONDITION</b>	4 Poor
<b>LOCATION:</b>	51.81 MILE POINT	<b>YEAR BUILT</b>	1955	<b>DECK CONDITION</b>	5 Fair
<b>BRIDGE NAME</b>	PRESUMPCOT RIVER S	<b>SPAN MATERIAL</b>	1 Steel	<b>CHANNEL CONDITION:</b>	5 Fair
<b>OWNER:</b>	8 ME TPK	<b>SPAN TYPE:</b>	1 Girder	<b>CULVERT CONDITION:</b>	N Not Applicable
<b>MAINTAINER</b>	8 ME TPK	<b>NUMBER OF MAIN SPANS:</b>	2	<b>APPROACH CONDITION:</b>	
<b>FEATURE ON:</b>	MTPK (SB)	<b>STRUCTURE LENGTH IN FEET</b>	165	<b>DATE OF INSPECTION:</b>	5/18/2008
<b>FEATURE UNDER</b>	PRESUMPCOT RIVER			<b>FEDERAL SUFFICIENCY RATING</b>	41.3
<b>ROAD INV NO:</b>	000000095S	<b>POSTING STATUS:</b>	1 Open		
<b>ROUTE NO:</b>	95	<b>POSTING TYPE:</b>	0 None needed		
<b>ROAD WIDTH</b>	30				
	<b>FEET</b>				
<b>CLASS:</b>	MAINE TURNPIKE AUTHORITY	<b>FEDERAL BRIDGE INDICATOR:</b>	Y		

## Structures in the Municipality of Portland

				CONDITION RATINGS	
<b>TOWN1:</b>	Portland	<b>TOWN2</b>	No town 2	<b>SUBSTRUCTURE CONDITION</b>	7      Good
<b>BRIDGE NO.:</b>	0820	<b>MAINT REGION</b>	Southern	<b>SUPERSTRUCTURE CONDITION</b>	7      Good
<b>LOCATION:</b>	0.1 MI S OF JCT I295 SB	<b>YEAR BUILT</b>	1990	<b>DECK CONDITION</b>	7      Good
<b>BRIDGE NAME</b>	WASHINGTON AVE SB	<b>SPAN MATERIAL</b>	2 Concrete	<b>CHANNEL CONDITION:</b>	8      Very Good
<b>OWNER:</b>	1 State DOT	<b>SPAN TYPE:</b>	1 Girder	<b>CULVERT CONDITION:</b>	N      Not Applicable
<b>MAINTAINER</b>	1 State DOT	<b>NUMBER OF MAIN SPANS:</b>	3	<b>APPROACH CONDITION:</b>	7      Good
<b>FEATURE ON:</b>	WASHINGTON AVE SB	<b>STRUCTURE LENGTH IN FEET</b>	405	<b>DATE OF INSPECTION:</b>	1/26/2010
<b>FEATURE UNDER</b>	I295NB&SB&ECOMMERC			<b>FEDERAL SUFFICIENCY RATING</b>	95.1
<b>ROAD INV NO:</b>	000000026S	<b>POSTING STATUS:</b>	1 Open		
<b>ROUTE NO:</b>	26	<b>POSTING TYPE:</b>	0 None needed		
<b>ROAD WIDTH</b>	36				
	<b>FEET</b>				
<b>CLASS:</b>	BRIDGE ON STATE HIGHWAY	<b>FEDERAL BRIDGE INDICATOR:</b>	Y		

## Structures in the Municipality of Portland

				CONDITION RATINGS	
<b>TOWN1:</b>	Portland	<b>TOWN2</b>	No town 2	<b>SUBSTRUCTURE CONDITION</b>	N      Not Applicable
<b>BRIDGE NO.:</b>	0353	<b>MAINT REGION</b>	Southern	<b>SUPERSTRUCTURE CONDITION</b>	N      Not Applicable
<b>LOCATION:</b>	45.54	<b>YEAR BUILT</b>	1955	<b>DECK CONDITION</b>	N      Not Applicable
<b>BRIDGE NAME</b>	FORE RIVER	<b>SPAN MATERIAL</b>	2 Concrete	<b>CHANNEL CONDITION:</b>	6      Satisfactory
<b>OWNER:</b>	8 ME TPK	<b>SPAN TYPE:</b>	4 Culvert	<b>CULVERT CONDITION:</b>	6      Satisfactory
<b>MAINTAINER</b>	8 ME TPK	<b>NUMBER OF MAIN SPANS:</b>	1	<b>APPROACH CONDITION:</b>	
<b>FEATURE ON:</b>	MAINE TURNPIKE	<b>STRUCTURE LENGTH IN FEET</b>	10	<b>DATE OF INSPECTION:</b>	5/1/2004
<b>FEATURE UNDER</b>	FORE RIVER			<b>FEDERAL SUFFICIENCY RATING</b>	70.5
<b>ROAD INV NO:</b>	000000095X	<b>POSTING STATUS:</b>	1 Open		
<b>ROUTE NO:</b>	95	<b>POSTING TYPE:</b>			
<b>ROAD WIDTH</b>	0				
	<b>FEET</b>				
<b>CLASS:</b>	MAINE TURNPIKE AUTHORITY	<b>FEDERAL BRIDGE INDICATOR:</b>	N		

## Structures in the Municipality of Portland

				CONDITION RATINGS	
<b>TOWN1:</b>	Portland	<b>TOWN2</b>	No town 2	<b>SUBSTRUCTURE CONDITION</b>	N      Not Applicable
<b>BRIDGE NO.:</b>	0360	<b>MAINT REGION</b>	Southern	<b>SUPERSTRUCTURE CONDITION</b>	N      Not Applicable
<b>LOCATION:</b>	.2 MI S RTE 25(BRIGHT	<b>YEAR BUILT</b>	1974	<b>DECK CONDITION</b>	N      Not Applicable
<b>BRIDGE NAME</b>	WEBB STREET	<b>SPAN MATERIAL</b>	1 Steel	<b>CHANNEL CONDITION:</b>	7      Good
<b>OWNER:</b>	4 Municipal	<b>SPAN TYPE:</b>	4 Culvert	<b>CULVERT CONDITION:</b>	6      Satisfactory
<b>MAINTAINER</b>	4 Municipal	<b>NUMBER OF MAIN SPANS:</b>	1	<b>APPROACH CONDITION:</b>	5      Fair
<b>FEATURE ON:</b>	WEBB STREET	<b>STRUCTURE LENGTH IN FEET</b>	12	<b>DATE OF INSPECTION:</b>	1/26/2010
<b>FEATURE UNDER</b>	DRAINAGE			<b>FEDERAL SUFFICIENCY RATING</b>	83.4
<b>ROAD INV NO:</b>	0000560777	<b>POSTING STATUS:</b>	1 Open		
<b>ROUTE NO:</b>	0	<b>POSTING TYPE:</b>	0 None needed		
<b>ROAD WIDTH</b>	0				
	<b>FEET</b>				
<b>CLASS:</b>	MINOR SPAN ON TOWN WAY	<b>FEDERAL BRIDGE INDICATOR:</b>	N		

## Structures in the Municipality of Portland

				CONDITION RATINGS	
<b>TOWN1:</b>	Portland	<b>TOWN2</b>	No town 2	<b>SUBSTRUCTURE CONDITION</b>	N      Not Applicable
<b>BRIDGE NO.:</b>	0366	<b>MAINT REGION</b>	Southern	<b>SUPERSTRUCTURE CONDITION</b>	N      Not Applicable
<b>LOCATION:</b>	0.1 MI S RT 25	<b>YEAR BUILT</b>	2006	<b>DECK CONDITION</b>	N      Not Applicable
<b>BRIDGE NAME</b>	LUCAS STREET	<b>SPAN MATERIAL</b>	7 Precast Concrete	<b>CHANNEL CONDITION:</b>	8      Very Good
<b>OWNER:</b>	4 Municipal	<b>SPAN TYPE:</b>	7 Rigid Frame	<b>CULVERT CONDITION:</b>	8      Very Good
<b>MAINTAINER</b>	4 Municipal	<b>NUMBER OF MAIN SPANS:</b>	1	<b>APPROACH CONDITION:</b>	8      Very Good
<b>FEATURE ON:</b>	LUCAS STREET	<b>STRUCTURE LENGTH IN FEET</b>	22	<b>DATE OF INSPECTION:</b>	1/27/2010
<b>FEATURE UNDER</b>	CAPISIC BROOK			<b>FEDERAL SUFFICIENCY RATING</b>	100
<b>ROAD INV NO:</b>	0000560459	<b>POSTING STATUS:</b>	1 Open		
<b>ROUTE NO:</b>	0	<b>POSTING TYPE:</b>	0 None needed		
<b>ROAD WIDTH</b>	30				
	<b>FEET</b>				
<b>CLASS:</b>	MINOR SPAN ON TOWN WAY	<b>FEDERAL BRIDGE INDICATOR:</b>	Y		

## Structures in the Municipality of Portland

				CONDITION RATINGS	
<b>TOWN1:</b>	Portland	<b>TOWN2</b>	Falmouth	<b>SUBSTRUCTURE CONDITION</b>	N      Not Applicable
<b>BRIDGE NO.:</b>	0371	<b>MAINT REGION</b>	Southern	<b>SUPERSTRUCTURE CONDITION</b>	N      Not Applicable
<b>LOCATION:</b>	TOWNLINE	<b>YEAR BUILT</b>	1969	<b>DECK CONDITION</b>	N      Not Applicable
<b>BRIDGE NAME</b>	BRIDGE AT STA. 98&88	<b>SPAN MATERIAL</b>	1 Steel	<b>CHANNEL CONDITION:</b>	5      Fair
<b>OWNER:</b>	1 State DOT	<b>SPAN TYPE:</b>	4 Culvert	<b>CULVERT CONDITION:</b>	3      Serious
<b>MAINTAINER</b>	1 State DOT	<b>NUMBER OF MAIN SPANS:</b>	2	<b>APPROACH CONDITION:</b>	8      Very Good
<b>FEATURE ON:</b>	295 NB&SB	<b>STRUCTURE LENGTH IN FEET</b>	14	<b>DATE OF INSPECTION:</b>	1/24/2001
<b>FEATURE UNDER</b>	PRESUMPCOTT RIVER			<b>FEDERAL SUFFICIENCY RATING</b>	49.3
<b>ROAD INV NO:</b>	000000295X	<b>POSTING STATUS:</b>	1 Open		
<b>ROUTE NO:</b>	295	<b>POSTING TYPE:</b>	0 None needed		
<b>ROAD WIDTH</b>	0				<b>FEET</b>
<b>CLASS:</b>		<b>FEDERAL BRIDGE INDICATOR:</b>	N		

## Structures in the Municipality of Portland

			CONDITION RATINGS	
<b>TOWN1:</b>	Portland	<b>TOWN2</b>	No town 2	<b>SUBSTRUCTURE CONDITION</b> <span style="border: 1px solid black; padding: 2px 10px;">7</span> <span style="border: 1px solid black; padding: 2px 10px;">Good</span>
<b>BRIDGE NO.:</b>	0815	<b>MAINT REGION</b>	Southern	<b>SUPERSTRUCTURE CONDITION</b> <span style="border: 1px solid black; padding: 2px 10px;">7</span> <span style="border: 1px solid black; padding: 2px 10px;">Good</span>
<b>LOCATION:</b>	0.1 MI E NB & SB DIVER	<b>YEAR BUILT</b>	1987	<b>DECK CONDITION</b> <span style="border: 1px solid black; padding: 2px 10px;">7</span> <span style="border: 1px solid black; padding: 2px 10px;">Good</span>
<b>BRIDGE NAME</b>	BAXTER BLVD NB OVR	<b>SPAN MATERIAL</b>	2 Concrete	<b>CHANNEL CONDITION:</b> <span style="border: 1px solid black; padding: 2px 10px;">8</span> <span style="border: 1px solid black; padding: 2px 10px;">Very Good</span>
<b>OWNER:</b>	1 State DOT	<b>SPAN TYPE:</b>	1 Girder	<b>CULVERT CONDITION:</b> <span style="border: 1px solid black; padding: 2px 10px;">N</span> <span style="border: 1px solid black; padding: 2px 10px;">Not Applicable</span>
<b>MAINTAINER</b>	1 State DOT	<b>NUMBER OF MAIN SPANS:</b>	4	<b>APPROACH CONDITION:</b> <span style="border: 1px solid black; padding: 2px 10px;">7</span> <span style="border: 1px solid black; padding: 2px 10px;">Good</span>
<b>FEATURE ON:</b>	US1 (BAXTER BLVD)	<b>STRUCTURE LENGTH IN FEET</b>	478	<b>DATE OF INSPECTION:</b> <span style="border: 1px solid black; padding: 2px 10px;">1/26/2010</span>
<b>FEATURE UNDER</b>	I295 & WASH AVE NB &			<b>FEDERAL SUFFICIENCY RATING</b> <span style="border: 1px solid black; padding: 2px 10px;">80</span>
<b>ROAD INV NO:</b>	0003201022	<b>POSTING STATUS:</b>	1 Open	
<b>ROUTE NO:</b>	0	<b>POSTING TYPE:</b>	0 None needed	
<b>ROAD WIDTH</b>	28			<b>FEET</b>
<b>CLASS:</b>	BRIDGE ON STATE HIGHWAY	<b>FEDERAL BRIDGE INDICATOR:</b>	Y	

## Structures in the Municipality of Portland

				CONDITION RATINGS	
<b>TOWN1:</b>	Portland	<b>TOWN2</b>	No town 2	<b>SUBSTRUCTURE CONDITION</b>	7      Good
<b>BRIDGE NO.:</b>	0352	<b>MAINT REGION</b>	Southern	<b>SUPERSTRUCTURE CONDITION</b>	6      Satisfactory
<b>LOCATION:</b>	51.6 MILE POINT	<b>YEAR BUILT</b>	1955	<b>DECK CONDITION</b>	5      Fair
<b>BRIDGE NAME</b>	FALMOUTH INTER	<b>SPAN MATERIAL</b>	1 Steel	<b>CHANNEL CONDITION:</b>	
<b>OWNER:</b>	8 ME TPK	<b>SPAN TYPE:</b>	1 Girder	<b>CULVERT CONDITION:</b>	N      Not Applicable
<b>MAINTAINER</b>	8 ME TPK	<b>NUMBER OF MAIN SPANS:</b>	6	<b>APPROACH CONDITION:</b>	
<b>FEATURE ON:</b>	FALMOUTH SPUR INTR	<b>STRUCTURE LENGTH IN FEET</b>	398	<b>DATE OF INSPECTION:</b>	5/18/2008
<b>FEATURE UNDER</b>	MTPK			<b>FEDERAL SUFFICIENCY RATING</b>	86.8
<b>ROAD INV NO:</b>	00005B0393	<b>POSTING STATUS:</b>	3 Posted		
<b>ROUTE NO:</b>	0	<b>POSTING TYPE:</b>	3 Underclearance Limit		
<b>ROAD WIDTH</b>	46				
	<b>FEET</b>				
<b>CLASS:</b>	MAINE TURNPIKE AUTHORITY	<b>FEDERAL BRIDGE INDICATOR:</b>	Y		

## Structures in the Municipality of Portland

				CONDITION RATINGS	
<b>TOWN1:</b>	Portland	<b>TOWN2</b>	No town 2	<b>SUBSTRUCTURE CONDITION</b>	7      Good
<b>BRIDGE NO.:</b>	0817	<b>MAINT REGION</b>	Southern	<b>SUPERSTRUCTURE CONDITION</b>	8      Very Good
<b>LOCATION:</b>	0.1 MI NE NB&SB CONV	<b>YEAR BUILT</b>	1987	<b>DECK CONDITION</b>	8      Very Good
<b>BRIDGE NAME</b>	BAXTER BLVD SB/WAS	<b>SPAN MATERIAL</b>	2 Concrete	<b>CHANNEL CONDITION:</b>	8      Very Good
<b>OWNER:</b>	1 State DOT	<b>SPAN TYPE:</b>	1 Girder	<b>CULVERT CONDITION:</b>	N      Not Applicable
<b>MAINTAINER</b>	1 State DOT	<b>NUMBER OF MAIN SPANS:</b>	2	<b>APPROACH CONDITION:</b>	8      Very Good
<b>FEATURE ON:</b>	US1 (BAXTER BLVD)	<b>STRUCTURE LENGTH IN FEET</b>	282	<b>DATE OF INSPECTION:</b>	1/26/2010
<b>FEATURE UNDER</b>	WASHINGTON AVE NB &			<b>FEDERAL SUFFICIENCY RATING</b>	95.2
<b>ROAD INV NO:</b>	000321022S	<b>POSTING STATUS:</b>	1 Open		
<b>ROUTE NO:</b>	0	<b>POSTING TYPE:</b>	0 None needed		
<b>ROAD WIDTH</b>	28				
	<b>FEET</b>				
<b>CLASS:</b>	BRIDGE ON STATE HIGHWAY	<b>FEDERAL BRIDGE INDICATOR:</b>	Y		

## Structures in the Municipality of Portland

				<b>CONDITION RATINGS</b>		
<b>TOWN1:</b>	Portland	<b>TOWN2</b>	No town 2	<b>SUBSTRUCTURE CONDITION</b>	7	Good
<b>BRIDGE NO.:</b>	0349	<b>MAINT REGION</b>	Southern	<b>SUPERSTRUCTURE CONDITION</b>	6	Satisfactory
<b>LOCATION:</b>	49.0 MILE POINT	<b>YEAR BUILT</b>	1955	<b>DECK CONDITION</b>	6	Satisfactory
<b>BRIDGE NAME</b>	WARREN AVE NB	<b>SPAN MATERIAL</b>	1 Steel	<b>CHANNEL CONDITION:</b>		
<b>OWNER:</b>	8 ME TPK	<b>SPAN TYPE:</b>	1 Girder	<b>CULVERT CONDITION:</b>	N	Not Applicable
<b>MAINTAINER</b>	8 ME TPK	<b>NUMBER OF MAIN SPANS:</b>	3	<b>APPROACH CONDITION:</b>		
<b>FEATURE ON:</b>	MTPK (NB)	<b>STRUCTURE LENGTH IN FEET</b>	226	<b>DATE OF INSPECTION:</b>	5/14/2008	
<b>FEATURE UNDER</b>	WARREN AVE			<b>FEDERAL SUFFICIENCY RATING</b>	87.8	
<b>ROAD INV NO:</b>	000000095X	<b>POSTING STATUS:</b>	3 Posted			
<b>ROUTE NO:</b>	95	<b>POSTING TYPE:</b>	3 Underclearance Limit			
<b>ROAD WIDTH</b>	38	<b>FEET</b>				
<b>CLASS:</b>	MAINE TURNPIKE AUTHORITY	<b>FEDERAL BRIDGE INDICATOR:</b>	Y			

## Structures in the Municipality of Portland

				CONDITION RATINGS	
<b>TOWN1:</b>	Portland	<b>TOWN2</b>	No town 2	<b>SUBSTRUCTURE CONDITION</b>	7      Good
<b>BRIDGE NO.:</b>	1484	<b>MAINT REGION</b>	Southern	<b>SUPERSTRUCTURE CONDITION</b>	6      Satisfactory
<b>LOCATION:</b>	46.71 MILE POINT	<b>YEAR BUILT</b>	1955	<b>DECK CONDITION</b>	6      Satisfactory
<b>BRIDGE NAME</b>	STROUDWATER RIVER	<b>SPAN MATERIAL</b>	1 Steel	<b>CHANNEL CONDITION:</b>	8      Very Good
<b>OWNER:</b>	8 ME TPK	<b>SPAN TYPE:</b>	1 Girder	<b>CULVERT CONDITION:</b>	N      Not Applicable
<b>MAINTAINER</b>	8 ME TPK	<b>NUMBER OF MAIN SPANS:</b>	4	<b>APPROACH CONDITION:</b>	
<b>FEATURE ON:</b>	MTPK (SB)	<b>STRUCTURE LENGTH IN FEET</b>	300	<b>DATE OF INSPECTION:</b>	5/15/2008
<b>FEATURE UNDER</b>	STROUDWATER RIVER			<b>FEDERAL SUFFICIENCY RATING</b>	87.1
<b>ROAD INV NO:</b>	000000095S	<b>POSTING STATUS:</b>	1 Open		
<b>ROUTE NO:</b>	95	<b>POSTING TYPE:</b>	0 None needed		
<b>ROAD WIDTH</b>	38				
	<b>FEET</b>				
<b>CLASS:</b>	MAINE TURNPIKE AUTHORITY	<b>FEDERAL BRIDGE INDICATOR:</b>	Y		

## Structures in the Municipality of Portland

				<b>CONDITION RATINGS</b>	
<b>TOWN1:</b>	Portland	<b>TOWN2</b>	No town 2	<b>SUBSTRUCTURE CONDITION</b>	7      Good
<b>BRIDGE NO.:</b>	1485	<b>MAINT REGION</b>	Southern	<b>SUPERSTRUCTURE CONDITION</b>	6      Satisfactory
<b>LOCATION:</b>	47.91 MILE POINT	<b>YEAR BUILT</b>	1955	<b>DECK CONDITION</b>	6      Satisfactory
<b>BRIDGE NAME</b>	MTPK(SB)/MCRR	<b>SPAN MATERIAL</b>	1 Steel	<b>CHANNEL CONDITION:</b>	
<b>OWNER:</b>	8 ME TPK	<b>SPAN TYPE:</b>	1 Girder	<b>CULVERT CONDITION:</b>	N      Not Applicable
<b>MAINTAINER</b>	8 ME TPK	<b>NUMBER OF MAIN SPANS:</b>	3	<b>APPROACH CONDITION:</b>	
<b>FEATURE ON:</b>	MTPK SB	<b>STRUCTURE LENGTH IN FEET</b>	244	<b>DATE OF INSPECTION:</b>	5/18/2008
<b>FEATURE UNDER</b>	MCRR (SB)			<b>FEDERAL SUFFICIENCY RATING</b>	87.3
<b>ROAD INV NO:</b>	000000095S	<b>POSTING STATUS:</b>	3 Posted		
<b>ROUTE NO:</b>	95	<b>POSTING TYPE:</b>	3 Underclearance Limit		
<b>ROAD WIDTH</b>	38				
	<b>FEET</b>				
<b>CLASS:</b>	MAINE TURNPIKE AUTHORITY	<b>FEDERAL BRIDGE INDICATOR:</b>	Y		

## Structures in the Municipality of Portland

				CONDITION RATINGS	
<b>TOWN1:</b>	Portland	<b>TOWN2</b>	No town 2	<b>SUBSTRUCTURE CONDITION</b>	7      Good
<b>BRIDGE NO.:</b>	1486	<b>MAINT REGION</b>	Southern	<b>SUPERSTRUCTURE CONDITION</b>	7      Good
<b>LOCATION:</b>	49.01 MILE POINT	<b>YEAR BUILT</b>	1955	<b>DECK CONDITION</b>	7      Good
<b>BRIDGE NAME</b>	WARREN AVE SB	<b>SPAN MATERIAL</b>	1 Steel	<b>CHANNEL CONDITION:</b>	
<b>OWNER:</b>	8 ME TPK	<b>SPAN TYPE:</b>	1 Girder	<b>CULVERT CONDITION:</b>	N      Not Applicable
<b>MAINTAINER</b>	8 ME TPK	<b>NUMBER OF MAIN SPANS:</b>	3	<b>APPROACH CONDITION:</b>	
<b>FEATURE ON:</b>	MTPK	<b>STRUCTURE LENGTH IN FEET</b>	226	<b>DATE OF INSPECTION:</b>	5/14/2008
<b>FEATURE UNDER</b>	WARREN AVENUE (SB)			<b>FEDERAL SUFFICIENCY RATING</b>	70
<b>ROAD INV NO:</b>	000000095S	<b>POSTING STATUS:</b>	3 Posted		
<b>ROUTE NO:</b>	95	<b>POSTING TYPE:</b>	3 Underclearance Limit		
<b>ROAD WIDTH</b>	30				
	<b>FEET</b>				
<b>CLASS:</b>	MAINE TURNPIKE AUTHORITY	<b>FEDERAL BRIDGE INDICATOR:</b>	Y		

## Structures in the Municipality of Portland

				CONDITION RATINGS	
<b>TOWN1:</b>	Portland	<b>TOWN2</b>	No town 2	<b>SUBSTRUCTURE CONDITION</b>	6 Satisfactory
<b>BRIDGE NO.:</b>	1487	<b>MAINT REGION</b>	Southern	<b>SUPERSTRUCTURE CONDITION</b>	6 Satisfactory
<b>LOCATION:</b>	50.01 MILE POINT	<b>YEAR BUILT</b>	1955	<b>DECK CONDITION</b>	6 Satisfactory
<b>BRIDGE NAME</b>	MTPK SB FOREST AVE	<b>SPAN MATERIAL</b>	1 Steel	<b>CHANNEL CONDITION:</b>	
<b>OWNER:</b>	8 ME TPK	<b>SPAN TYPE:</b>	1 Girder	<b>CULVERT CONDITION:</b>	N Not Applicable
<b>MAINTAINER</b>	8 ME TPK	<b>NUMBER OF MAIN SPANS:</b>	3	<b>APPROACH CONDITION:</b>	
<b>FEATURE ON:</b>	MTPK (SB)	<b>STRUCTURE LENGTH IN FEET</b>	147	<b>DATE OF INSPECTION:</b>	5/14/2008
<b>FEATURE UNDER</b>	FOREST AVENUE			<b>FEDERAL SUFFICIENCY RATING</b>	94
<b>ROAD INV NO:</b>	000000095S	<b>POSTING STATUS:</b>	1 Open		
<b>ROUTE NO:</b>	95	<b>POSTING TYPE:</b>	0 None needed		
<b>ROAD WIDTH</b>	41				
	<b>FEET</b>				
<b>CLASS:</b>	MAINE TURNPIKE AUTHORITY	<b>FEDERAL BRIDGE INDICATOR:</b>	Y		

## Structures in the Municipality of Portland

				CONDITION RATINGS	
<b>TOWN1:</b>	Portland	<b>TOWN2</b>	No town 2	<b>SUBSTRUCTURE CONDITION</b>	7      Good
<b>BRIDGE NO.:</b>	1488	<b>MAINT REGION</b>	Southern	<b>SUPERSTRUCTURE CONDITION</b>	7      Good
<b>LOCATION:</b>	51.21 MILE POINT	<b>YEAR BUILT</b>	1955	<b>DECK CONDITION</b>	7      Good
<b>BRIDGE NAME</b>	MTPK SB RIVERSIDE ST	<b>SPAN MATERIAL</b>	1 Steel	<b>CHANNEL CONDITION:</b>	
<b>OWNER:</b>	8 ME TPK	<b>SPAN TYPE:</b>	1 Girder	<b>CULVERT CONDITION:</b>	N      Not Applicable
<b>MAINTAINER</b>	8 ME TPK	<b>NUMBER OF MAIN SPANS:</b>	3	<b>APPROACH CONDITION:</b>	
<b>FEATURE ON:</b>	MTPK (SB)	<b>STRUCTURE LENGTH IN FEET</b>	132	<b>DATE OF INSPECTION:</b>	5/14/2008
<b>FEATURE UNDER</b>	RIVERSIDE STREET			<b>FEDERAL SUFFICIENCY RATING</b>	96
<b>ROAD INV NO:</b>	000000095S	<b>POSTING STATUS:</b>	1 Open		
<b>ROUTE NO:</b>	95	<b>POSTING TYPE:</b>	0 None needed		
<b>ROAD WIDTH</b>	52				
	<b>FEET</b>				
<b>CLASS:</b>	MAINE TURNPIKE AUTHORITY	<b>FEDERAL BRIDGE INDICATOR:</b>	Y		

## Structures in the Municipality of Portland

				CONDITION RATINGS	
<b>TOWN1:</b>	Portland	<b>TOWN2</b>	No town 2	<b>SUBSTRUCTURE CONDITION</b>	7      Good
<b>BRIDGE NO.:</b>	0816	<b>MAINT REGION</b>	Southern	<b>SUPERSTRUCTURE CONDITION</b>	8      Very Good
<b>LOCATION:</b>	0.1 MI N BACK X'INGUK	<b>YEAR BUILT</b>	1987	<b>DECK CONDITION</b>	7      Good
<b>BRIDGE NAME</b>	I-295 OVER WASHINGTN	<b>SPAN MATERIAL</b>	2 Concrete	<b>CHANNEL CONDITION:</b>	8      Very Good
<b>OWNER:</b>	1 State DOT	<b>SPAN TYPE:</b>	1 Girder	<b>CULVERT CONDITION:</b>	N      Not Applicable
<b>MAINTAINER</b>	1 State DOT	<b>NUMBER OF MAIN SPANS:</b>	1	<b>APPROACH CONDITION:</b>	7      Good
<b>FEATURE ON:</b>	I-295 NB&SB	<b>STRUCTURE LENGTH IN FEET</b>	147	<b>DATE OF INSPECTION:</b>	1/26/2010
<b>FEATURE UNDER</b>	RTE 26 (WASH AVE) N B			<b>FEDERAL SUFFICIENCY RATING</b>	95.7
<b>ROAD INV NO:</b>	000000295X	<b>POSTING STATUS:</b>	1 Open		
<b>ROUTE NO:</b>	295	<b>POSTING TYPE:</b>	0 None needed		
<b>ROAD WIDTH</b>	84				
	<b>FEET</b>				
<b>CLASS:</b>	BRIDGE ON STATE HIGHWAY	<b>FEDERAL BRIDGE INDICATOR:</b>	Y		

## Structures in the Municipality of Portland

				CONDITION RATINGS	
<b>TOWN1:</b>	Portland	<b>TOWN2</b>	No town 2	<b>SUBSTRUCTURE CONDITION</b>	9      Excellent
<b>BRIDGE NO.:</b>	0343	<b>MAINT REGION</b>	Southern	<b>SUPERSTRUCTURE CONDITION</b>	8      Very Good
<b>LOCATION:</b>	46.4 MILE POINT	<b>YEAR BUILT</b>	1955	<b>DECK CONDITION</b>	8      Very Good
<b>BRIDGE NAME</b>	CONGRESS STREET	<b>SPAN MATERIAL</b>	1 Steel	<b>CHANNEL CONDITION:</b>	
<b>OWNER:</b>	8 ME TPK	<b>SPAN TYPE:</b>	1 Girder	<b>CULVERT CONDITION:</b>	N      Not Applicable
<b>MAINTAINER</b>	8 ME TPK	<b>NUMBER OF MAIN SPANS:</b>	4	<b>APPROACH CONDITION:</b>	
<b>FEATURE ON:</b>	CONGRESS ST/RTE 22	<b>STRUCTURE LENGTH IN FEET</b>	200	<b>DATE OF INSPECTION:</b>	5/13/2008
<b>FEATURE UNDER</b>	MTPK			<b>FEDERAL SUFFICIENCY RATING</b>	67.2
<b>ROAD INV NO:</b>	000000022X	<b>POSTING STATUS:</b>	3 Posted		
<b>ROUTE NO:</b>	22	<b>POSTING TYPE:</b>	3 Underclearance Limit		
<b>ROAD WIDTH</b>	30				
	<b>FEET</b>				
<b>CLASS:</b>	MAINE TURNPIKE AUTHORITY	<b>FEDERAL BRIDGE INDICATOR:</b>	Y		

## Structures in the Municipality of Portland

				CONDITION RATINGS	
<b>TOWN1:</b>	Portland	<b>TOWN2</b>	No town 2	<b>SUBSTRUCTURE CONDITION</b>	N      Not Applicable
<b>BRIDGE NO.:</b>	0320	<b>MAINT REGION</b>	Southern	<b>SUPERSTRUCTURE CONDITION</b>	N      Not Applicable
<b>LOCATION:</b>	0.4 MI W 1295	<b>YEAR BUILT</b>	1995	<b>DECK CONDITION</b>	N      Not Applicable
<b>BRIDGE NAME</b>	BAXTER BLVD EAST	<b>SPAN MATERIAL</b>	7 Precast Concrete	<b>CHANNEL CONDITION:</b>	8      Very Good
<b>OWNER:</b>	4 Municipal	<b>SPAN TYPE:</b>	4 Culvert	<b>CULVERT CONDITION:</b>	7      Good
<b>MAINTAINER</b>	4 Municipal	<b>NUMBER OF MAIN SPANS:</b>	1	<b>APPROACH CONDITION:</b>	7      Good
<b>FEATURE ON:</b>	BAXTER BLVD	<b>STRUCTURE LENGTH IN FEET</b>	13	<b>DATE OF INSPECTION:</b>	1/22/2010
<b>FEATURE UNDER</b>	FALL BROOK			<b>FEDERAL SUFFICIENCY RATING</b>	95.8
<b>ROAD INV NO:</b>	0003201021	<b>POSTING STATUS:</b>	1 Open		
<b>ROUTE NO:</b>	0	<b>POSTING TYPE:</b>	0 None needed		
<b>ROAD WIDTH</b>	0				
	<b>FEET</b>				
<b>CLASS:</b>	MINOR SPAN ON TOWN WAY	<b>FEDERAL BRIDGE INDICATOR:</b>	N		

## Structures in the Municipality of Portland

				CONDITION RATINGS	
<b>TOWN1:</b>	Portland	<b>TOWN2</b>	No town 2	<b>SUBSTRUCTURE CONDITION</b>	N      Not Applicable
<b>BRIDGE NO.:</b>	0321	<b>MAINT REGION</b>	Southern	<b>SUPERSTRUCTURE CONDITION</b>	N      Not Applicable
<b>LOCATION:</b>	.7 MI SE RT25-BRIGHTO	<b>YEAR BUILT</b>	2003	<b>DECK CONDITION</b>	N      Not Applicable
<b>BRIDGE NAME</b>	CAPISIC STREET	<b>SPAN MATERIAL</b>	7 Precast Concrete	<b>CHANNEL CONDITION:</b>	9      Excellent
<b>OWNER:</b>	1 State DOT	<b>SPAN TYPE:</b>	6 Arch	<b>CULVERT CONDITION:</b>	9      Excellent
<b>MAINTAINER</b>	1 State DOT	<b>NUMBER OF MAIN SPANS:</b>	1	<b>APPROACH CONDITION:</b>	8      Very Good
<b>FEATURE ON:</b>	CAPISIC STREET	<b>STRUCTURE LENGTH IN FEET</b>	26	<b>DATE OF INSPECTION:</b>	11/24/2009
<b>FEATURE UNDER</b>	CAPISIC POND OUTLET			<b>FEDERAL SUFFICIENCY RATING</b>	88.6
<b>ROAD INV NO:</b>	0000560109	<b>POSTING STATUS:</b>	1 Open		
<b>ROUTE NO:</b>	0	<b>POSTING TYPE:</b>	0 None needed		
<b>ROAD WIDTH</b>	0				
	<b>FEET</b>				
<b>CLASS:</b>	MINOR SPAN ON STATE AID ROAD	<b>FEDERAL BRIDGE INDICATOR:</b>	Y		

## Structures in the Municipality of Portland

				CONDITION RATINGS	
<b>TOWN1:</b>	Portland	<b>TOWN2</b>	No town 2	<b>SUBSTRUCTURE CONDITION</b>	5      Fair
<b>BRIDGE NO.:</b>	0326	<b>MAINT REGION</b>	Southern	<b>SUPERSTRUCTURE CONDITION</b>	N      Not Applicable
<b>LOCATION:</b>	200 FT W ST JOHNS ST	<b>YEAR BUILT</b>	1930	<b>DECK CONDITION</b>	N      Not Applicable
<b>BRIDGE NAME</b>	PARK AVE UNDERPASS	<b>SPAN MATERIAL</b>	1 Steel	<b>CHANNEL CONDITION:</b>	5      Fair
<b>OWNER:</b>	6 Railroad	<b>SPAN TYPE:</b>	2 Girder - floor beam	<b>CULVERT CONDITION:</b>	N      Not Applicable
<b>MAINTAINER</b>	6 Railroad	<b>NUMBER OF MAIN SPANS:</b>	3	<b>APPROACH CONDITION:</b>	
<b>FEATURE ON:</b>	MAINE CENTRAL RAIL	<b>STRUCTURE LENGTH IN FEET</b>	78	<b>DATE OF INSPECTION:</b>	10/30/2009
<b>FEATURE UNDER</b>	PARK AVENUE			<b>FEDERAL SUFFICIENCY RATING</b>	-1
<b>ROAD INV NO:</b>		<b>POSTING STATUS:</b>	3 Posted		
<b>ROUTE NO:</b>		<b>POSTING TYPE:</b>	3 Underclearance Limit		
<b>ROAD WIDTH</b>					
	<b>FEET</b>				
<b>CLASS:</b>		<b>FEDERAL BRIDGE INDICATOR:</b>	Y		

## Structures in the Municipality of Portland

				CONDITION RATINGS	
<b>TOWN1:</b>	Portland	<b>TOWN2</b>	No town 2	<b>SUBSTRUCTURE CONDITION</b>	6 Satisfactory
<b>BRIDGE NO.:</b>	0327	<b>MAINT REGION</b>	Southern	<b>SUPERSTRUCTURE CONDITION</b>	N Not Applicable
<b>LOCATION:</b>	.3 MI NW CONGRESS ST	<b>YEAR BUILT</b>	1900	<b>DECK CONDITION</b>	N Not Applicable
<b>BRIDGE NAME</b>	ST JOHN ST UNDERPAS	<b>SPAN MATERIAL</b>	1 Steel	<b>CHANNEL CONDITION:</b>	7 Good
<b>OWNER:</b>	6 Railroad	<b>SPAN TYPE:</b>	5 Truss	<b>CULVERT CONDITION:</b>	N Not Applicable
<b>MAINTAINER</b>	6 Railroad	<b>NUMBER OF MAIN SPANS:</b>	1	<b>APPROACH CONDITION:</b>	
<b>FEATURE ON:</b>	MAINE CENTRAL RAIL	<b>STRUCTURE LENGTH IN FEET</b>	117	<b>DATE OF INSPECTION:</b>	10/30/2009
<b>FEATURE UNDER</b>	SAINT JOHN STREET			<b>FEDERAL SUFFICIENCY RATING</b>	-1
<b>ROAD INV NO:</b>		<b>POSTING STATUS:</b>	1 Open		
<b>ROUTE NO:</b>		<b>POSTING TYPE:</b>	0 None needed		
<b>ROAD WIDTH</b>					
	<b>FEET</b>				
<b>CLASS:</b>		<b>FEDERAL BRIDGE INDICATOR:</b>	Y		

## Structures in the Municipality of Portland

				CONDITION RATINGS	
<b>TOWN1:</b>	Portland	<b>TOWN2</b>	No town 2	<b>SUBSTRUCTURE CONDITION</b>	N      Not Applicable
<b>BRIDGE NO.:</b>	0328	<b>MAINT REGION</b>	Southern	<b>SUPERSTRUCTURE CONDITION</b>	N      Not Applicable
<b>LOCATION:</b>	ADJINT BEACH,CLARK	<b>YEAR BUILT</b>	1900	<b>DECK CONDITION</b>	N      Not Applicable
<b>BRIDGE NAME</b>	CLARK ST. OVERPASS	<b>SPAN MATERIAL</b>	4 Stone	<b>CHANNEL CONDITION:</b>	6      Satisfactory
<b>OWNER:</b>	1 State DOT	<b>SPAN TYPE:</b>	6 Arch	<b>CULVERT CONDITION:</b>	4      Poor
<b>MAINTAINER</b>	1 State DOT	<b>NUMBER OF MAIN SPANS:</b>	1	<b>APPROACH CONDITION:</b>	8      Very Good
<b>FEATURE ON:</b>	BEACH ST & BAY BR	<b>STRUCTURE LENGTH IN FEET</b>	60	<b>DATE OF INSPECTION:</b>	12/30/2009
<b>FEATURE UNDER</b>	PTRR (ABANDONED)			<b>FEDERAL SUFFICIENCY RATING</b>	62.8
<b>ROAD INV NO:</b>	0000560816	<b>POSTING STATUS:</b>	1 Open		
<b>ROUTE NO:</b>	0	<b>POSTING TYPE:</b>	0 None needed		
<b>ROAD WIDTH</b>	0				
	<b>FEET</b>				
<b>CLASS:</b>	BRIDGE ON TOWN WAY OR STATE AID ROAD	<b>FEDERAL BRIDGE INDICATOR:</b>	Y		

## Structures in the Municipality of Portland

				CONDITION RATINGS	
<b>TOWN1:</b>	Portland	<b>TOWN2</b>	No town 2	<b>SUBSTRUCTURE CONDITION</b>	7      Good
<b>BRIDGE NO.:</b>	0351	<b>MAINT REGION</b>	Southern	<b>SUPERSTRUCTURE CONDITION</b>	6      Satisfactory
<b>LOCATION:</b>	51.2 MILE POINT	<b>YEAR BUILT</b>	1955	<b>DECK CONDITION</b>	7      Good
<b>BRIDGE NAME</b>	RIVERSIDE NB	<b>SPAN MATERIAL</b>	1 Steel	<b>CHANNEL CONDITION:</b>	
<b>OWNER:</b>	8 ME TPK	<b>SPAN TYPE:</b>	1 Girder	<b>CULVERT CONDITION:</b>	N      Not Applicable
<b>MAINTAINER</b>	8 ME TPK	<b>NUMBER OF MAIN SPANS:</b>	3	<b>APPROACH CONDITION:</b>	
<b>FEATURE ON:</b>	MTPK (NB)	<b>STRUCTURE LENGTH IN FEET</b>	132	<b>DATE OF INSPECTION:</b>	5/14/2008
<b>FEATURE UNDER</b>	RIVERSIDE ST			<b>FEDERAL SUFFICIENCY RATING</b>	86.8
<b>ROAD INV NO:</b>	000000095X	<b>POSTING STATUS:</b>	1 Open		
<b>ROUTE NO:</b>	95	<b>POSTING TYPE:</b>	0 None needed		
<b>ROAD WIDTH</b>	41				
	<b>FEET</b>				
<b>CLASS:</b>	MAINE TURNPIKE AUTHORITY	<b>FEDERAL BRIDGE INDICATOR:</b>	Y		

## Structures in the Municipality of Portland

				CONDITION RATINGS	
<b>TOWN1:</b>	Portland	<b>TOWN2</b>	No town 2	<b>SUBSTRUCTURE CONDITION</b>	N      Not Applicable
<b>BRIDGE NO.:</b>	0340	<b>MAINT REGION</b>	Southern	<b>SUPERSTRUCTURE CONDITION</b>	N      Not Applicable
<b>LOCATION:</b>	0.2 MI. E. RT. 100	<b>YEAR BUILT</b>	2005	<b>DECK CONDITION</b>	N      Not Applicable
<b>BRIDGE NAME</b>	RAY STREET	<b>SPAN MATERIAL</b>	7 Precast Concrete	<b>CHANNEL CONDITION:</b>	8      Very Good
<b>OWNER:</b>	4 Municipal	<b>SPAN TYPE:</b>	6 Arch	<b>CULVERT CONDITION:</b>	8      Very Good
<b>MAINTAINER</b>	4 Municipal	<b>NUMBER OF MAIN SPANS:</b>	1	<b>APPROACH CONDITION:</b>	8      Very Good
<b>FEATURE ON:</b>	RAY STREET	<b>STRUCTURE LENGTH IN FEET</b>	25	<b>DATE OF INSPECTION:</b>	1/27/2010
<b>FEATURE UNDER</b>	FALL BROOK			<b>FEDERAL SUFFICIENCY RATING</b>	99.7
<b>ROAD INV NO:</b>	0000560612	<b>POSTING STATUS:</b>	1 Open		
<b>ROUTE NO:</b>	0	<b>POSTING TYPE:</b>	0 None needed		
<b>ROAD WIDTH</b>	0				
	<b>FEET</b>				
<b>CLASS:</b>	MINOR SPAN ON TOWN WAY	<b>FEDERAL BRIDGE INDICATOR:</b>	Y		

## Structures in the Municipality of Portland

				CONDITION RATINGS	
<b>TOWN1:</b>	Portland	<b>TOWN2</b>	No town 2	<b>SUBSTRUCTURE CONDITION</b>	N      Not Applicable
<b>BRIDGE NO.:</b>	0146	<b>MAINT REGION</b>	Southern	<b>SUPERSTRUCTURE CONDITION</b>	N      Not Applicable
<b>LOCATION:</b>	53.5 MILE POINT	<b>YEAR BUILT</b>	1955	<b>DECK CONDITION</b>	N      Not Applicable
<b>BRIDGE NAME</b>	DEERING BROOK	<b>SPAN MATERIAL</b>	2 Concrete	<b>CHANNEL CONDITION:</b>	7      Good
<b>OWNER:</b>	8 ME TPK	<b>SPAN TYPE:</b>	4 Culvert	<b>CULVERT CONDITION:</b>	6      Satisfactory
<b>MAINTAINER</b>	8 ME TPK	<b>NUMBER OF MAIN SPANS:</b>	1	<b>APPROACH CONDITION:</b>	
<b>FEATURE ON:</b>	MTPK	<b>STRUCTURE LENGTH IN FEET</b>	6	<b>DATE OF INSPECTION:</b>	4/19/2006
<b>FEATURE UNDER</b>	DEERING BROOK			<b>FEDERAL SUFFICIENCY RATING</b>	73.4
<b>ROAD INV NO:</b>	000000095X	<b>POSTING STATUS:</b>	1 Open		
<b>ROUTE NO:</b>	95	<b>POSTING TYPE:</b>	0 None needed		
<b>ROAD WIDTH</b>	0				
	<b>FEET</b>				
<b>CLASS:</b>	MAINE TURNPIKE AUTHORITY	<b>FEDERAL BRIDGE INDICATOR:</b>	N		

## Structures in the Municipality of Portland

				CONDITION RATINGS	
<b>TOWN1:</b>	Portland	<b>TOWN2</b>	No town 2	<b>SUBSTRUCTURE CONDITION</b>	6 Satisfactory
<b>BRIDGE NO.:</b>	0344	<b>MAINT REGION</b>	Southern	<b>SUPERSTRUCTURE CONDITION</b>	6 Satisfactory
<b>LOCATION:</b>	46.7 MILE POINT	<b>YEAR BUILT</b>	1955	<b>DECK CONDITION</b>	6 Satisfactory
<b>BRIDGE NAME</b>	STROUDWATER RIVER	<b>SPAN MATERIAL</b>	1 Steel	<b>CHANNEL CONDITION:</b>	8 Very Good
<b>OWNER:</b>	8 ME TPK	<b>SPAN TYPE:</b>	1 Girder	<b>CULVERT CONDITION:</b>	N Not Applicable
<b>MAINTAINER</b>	8 ME TPK	<b>NUMBER OF MAIN SPANS:</b>	4	<b>APPROACH CONDITION:</b>	
<b>FEATURE ON:</b>	MTPK NB	<b>STRUCTURE LENGTH IN FEET</b>	300	<b>DATE OF INSPECTION:</b>	5/15/2008
<b>FEATURE UNDER</b>	STROUDWATER RIVER			<b>FEDERAL SUFFICIENCY RATING</b>	88.4
<b>ROAD INV NO:</b>	000000095X	<b>POSTING STATUS:</b>	1 Open		
<b>ROUTE NO:</b>	95	<b>POSTING TYPE:</b>	0 None needed		
<b>ROAD WIDTH</b>	38				
	<b>FEET</b>				
<b>CLASS:</b>	MAINE TURNPIKE AUTHORITY	<b>FEDERAL BRIDGE INDICATOR:</b>	Y		

## Structures in the Municipality of Portland

				CONDITION RATINGS	
<b>TOWN1:</b>	Portland	<b>TOWN2</b>	No town 2	<b>SUBSTRUCTURE CONDITION</b>	9      Excellent
<b>BRIDGE NO.:</b>	0345	<b>MAINT REGION</b>	Southern	<b>SUPERSTRUCTURE CONDITION</b>	9      Excellent
<b>LOCATION:</b>	47.1 MILE POINT	<b>YEAR BUILT</b>	2006	<b>DECK CONDITION</b>	8      Very Good
<b>BRIDGE NAME</b>	WESTBROOKST	<b>SPAN MATERIAL</b>	1 Steel	<b>CHANNEL CONDITION:</b>	
<b>OWNER:</b>	8 ME TPK	<b>SPAN TYPE:</b>	1 Girder	<b>CULVERT CONDITION:</b>	N      Not Applicable
<b>MAINTAINER</b>	8 ME TPK	<b>NUMBER OF MAIN SPANS:</b>	2	<b>APPROACH CONDITION:</b>	
<b>FEATURE ON:</b>	WESTBROOK ST	<b>STRUCTURE LENGTH IN FEET</b>	208	<b>DATE OF INSPECTION:</b>	5/13/2008
<b>FEATURE UNDER</b>	MTPK			<b>FEDERAL SUFFICIENCY RATING</b>	86.2
<b>ROAD INV NO:</b>	0000560784	<b>POSTING STATUS:</b>	1 Open		
<b>ROUTE NO:</b>	0	<b>POSTING TYPE:</b>	0 None needed		
<b>ROAD WIDTH</b>	40				
	<b>FEET</b>				
<b>CLASS:</b>	MAINE TURNPIKE AUTHORITY	<b>FEDERAL BRIDGE INDICATOR:</b>	Y		

## Structures in the Municipality of Portland

				CONDITION RATINGS	
<b>TOWN1:</b>	Portland	<b>TOWN2</b>	No town 2	<b>SUBSTRUCTURE CONDITION</b>	7      Good
<b>BRIDGE NO.:</b>	0346	<b>MAINT REGION</b>	Southern	<b>SUPERSTRUCTURE CONDITION</b>	6      Satisfactory
<b>LOCATION:</b>	47.9 MILE POINT	<b>YEAR BUILT</b>	1955	<b>DECK CONDITION</b>	6      Satisfactory
<b>BRIDGE NAME</b>	MCRR NB	<b>SPAN MATERIAL</b>	1 Steel	<b>CHANNEL CONDITION:</b>	
<b>OWNER:</b>	8 ME TPK	<b>SPAN TYPE:</b>	1 Girder	<b>CULVERT CONDITION:</b>	N      Not Applicable
<b>MAINTAINER</b>	8 ME TPK	<b>NUMBER OF MAIN SPANS:</b>	3	<b>APPROACH CONDITION:</b>	
<b>FEATURE ON:</b>	MTPK	<b>STRUCTURE LENGTH IN FEET</b>	242	<b>DATE OF INSPECTION:</b>	5/18/2008
<b>FEATURE UNDER</b>	MCRR (NB)			<b>FEDERAL SUFFICIENCY RATING</b>	87.5
<b>ROAD INV NO:</b>	000000095X	<b>POSTING STATUS:</b>	3 Posted		
<b>ROUTE NO:</b>	95	<b>POSTING TYPE:</b>	3 Underclearance Limit		
<b>ROAD WIDTH</b>	38				
	<b>FEET</b>				
<b>CLASS:</b>	MAINE TURNPIKE AUTHORITY	<b>FEDERAL BRIDGE INDICATOR:</b>	Y		

## Structures in the Municipality of Portland

				CONDITION RATINGS	
<b>TOWN1:</b>	Portland	<b>TOWN2</b>	No town 2	<b>SUBSTRUCTURE CONDITION</b>	8      Very Good
<b>BRIDGE NO.:</b>	0347	<b>MAINT REGION</b>	Southern	<b>SUPERSTRUCTURE CONDITION</b>	8      Very Good
<b>LOCATION:</b>	48.3 MILE POINT	<b>YEAR BUILT</b>	1955	<b>DECK CONDITION</b>	8      Very Good
<b>BRIDGE NAME</b>	BRIGHTON AVE	<b>SPAN MATERIAL</b>	1 Steel	<b>CHANNEL CONDITION:</b>	
<b>OWNER:</b>	8 ME TPK	<b>SPAN TYPE:</b>	1 Girder	<b>CULVERT CONDITION:</b>	N      Not Applicable
<b>MAINTAINER</b>	8 ME TPK	<b>NUMBER OF MAIN SPANS:</b>	4	<b>APPROACH CONDITION:</b>	
<b>FEATURE ON:</b>	BRIGHTON AVE	<b>STRUCTURE LENGTH IN FEET</b>	212	<b>DATE OF INSPECTION:</b>	5/15/2008
<b>FEATURE UNDER</b>	MTPK			<b>FEDERAL SUFFICIENCY RATING</b>	69.8
<b>ROAD INV NO:</b>	000000025C	<b>POSTING STATUS:</b>	3 Posted		
<b>ROUTE NO:</b>	25	<b>POSTING TYPE:</b>	3 Underclearance Limit		
<b>ROAD WIDTH</b>	52				
	<b>FEET</b>				
<b>CLASS:</b>	MAINE TURNPIKE AUTHORITY	<b>FEDERAL BRIDGE INDICATOR:</b>	Y		

## Structures in the Municipality of Portland

				CONDITION RATINGS	
<b>TOWN1:</b>	Portland	<b>TOWN2</b>	No town 2	<b>SUBSTRUCTURE CONDITION</b>	6 Satisfactory
<b>BRIDGE NO.:</b>	0348	<b>MAINT REGION</b>	Southern	<b>SUPERSTRUCTURE CONDITION</b>	4 Poor
<b>LOCATION:</b>	48.5 MILE POINT	<b>YEAR BUILT</b>	1955	<b>DECK CONDITION</b>	4 Poor
<b>BRIDGE NAME</b>	PORTLAND WESTBROO	<b>SPAN MATERIAL</b>	1 Steel	<b>CHANNEL CONDITION:</b>	
<b>OWNER:</b>	8 ME TPK	<b>SPAN TYPE:</b>	1 Girder	<b>CULVERT CONDITION:</b>	N Not Applicable
<b>MAINTAINER</b>	8 ME TPK	<b>NUMBER OF MAIN SPANS:</b>	4	<b>APPROACH CONDITION:</b>	
<b>FEATURE ON:</b>	RIVERSIDE/LARRABEE	<b>STRUCTURE LENGTH IN FEET</b>	333	<b>DATE OF INSPECTION:</b>	5/18/2008
<b>FEATURE UNDER</b>	MTPK			<b>FEDERAL SUFFICIENCY RATING</b>	56.8
<b>ROAD INV NO:</b>	00005A0394	<b>POSTING STATUS:</b>	3 Posted		
<b>ROUTE NO:</b>	0	<b>POSTING TYPE:</b>	3 Underclearance Limit		
<b>ROAD WIDTH</b>	32				
	<b>FEET</b>				
<b>CLASS:</b>	MAINE TURNPIKE AUTHORITY	<b>FEDERAL BRIDGE INDICATOR:</b>	Y		

## Structures in the Municipality of Portland

				<b>CONDITION RATINGS</b>	
<b>TOWN1:</b>	Portland	<b>TOWN2</b>	No town 2	<b>SUBSTRUCTURE CONDITION</b>	7      Good
<b>BRIDGE NO.:</b>	0350	<b>MAINT REGION</b>	Southern	<b>SUPERSTRUCTURE CONDITION</b>	6      Satisfactory
<b>LOCATION:</b>	50.0 MILE POINT	<b>YEAR BUILT</b>	1955	<b>DECK CONDITION</b>	7      Good
<b>BRIDGE NAME</b>	FOREST AVE NB	<b>SPAN MATERIAL</b>	1 Steel	<b>CHANNEL CONDITION:</b>	
<b>OWNER:</b>	8 ME TPK	<b>SPAN TYPE:</b>	1 Girder	<b>CULVERT CONDITION:</b>	N      Not Applicable
<b>MAINTAINER</b>	8 ME TPK	<b>NUMBER OF MAIN SPANS:</b>	3	<b>APPROACH CONDITION:</b>	
<b>FEATURE ON:</b>	MTPK (NB)	<b>STRUCTURE LENGTH IN FEET</b>	147	<b>DATE OF INSPECTION:</b>	5/14/2008
<b>FEATURE UNDER</b>	FOREST AVE			<b>FEDERAL SUFFICIENCY RATING</b>	88.8
<b>ROAD INV NO:</b>	000000095X	<b>POSTING STATUS:</b>	1 Open		
<b>ROUTE NO:</b>	95	<b>POSTING TYPE:</b>	0 None needed		
<b>ROAD WIDTH</b>	41				
	<b>FEET</b>				
<b>CLASS:</b>	MAINE TURNPIKE AUTHORITY	<b>FEDERAL BRIDGE INDICATOR:</b>	Y		

## Structures in the Municipality of Portland

				CONDITION RATINGS	
<b>TOWN1:</b>	Portland	<b>TOWN2</b>	No town 2	<b>SUBSTRUCTURE CONDITION</b>	8      Very Good
<b>BRIDGE NO.:</b>	0337	<b>MAINT REGION</b>	Southern	<b>SUPERSTRUCTURE CONDITION</b>	8      Very Good
<b>LOCATION:</b>	0.3 MI S RTE 25	<b>YEAR BUILT</b>	1996	<b>DECK CONDITION</b>	8      Very Good
<b>BRIDGE NAME</b>	ROWE AVENUE	<b>SPAN MATERIAL</b>	7 Precast Concrete	<b>CHANNEL CONDITION:</b>	8      Very Good
<b>OWNER:</b>	4 Municipal	<b>SPAN TYPE:</b>	6 Arch	<b>CULVERT CONDITION:</b>	N      Not Applicable
<b>MAINTAINER</b>	4 Municipal	<b>NUMBER OF MAIN SPANS:</b>	1	<b>APPROACH CONDITION:</b>	6      Satisfactory
<b>FEATURE ON:</b>	ROWE AVE	<b>STRUCTURE LENGTH IN FEET</b>	18	<b>DATE OF INSPECTION:</b>	1/26/2010
<b>FEATURE UNDER</b>	NASONS BROOK			<b>FEDERAL SUFFICIENCY RATING</b>	77.9
<b>ROAD INV NO:</b>	0000560630	<b>POSTING STATUS:</b>	1 Open		
<b>ROUTE NO:</b>	0	<b>POSTING TYPE:</b>	0 None needed		
<b>ROAD WIDTH</b>	23				
	<b>FEET</b>				
<b>CLASS:</b>	MINOR SPAN ON TOWN WAY	<b>FEDERAL BRIDGE INDICATOR:</b>	N		

## Structures in the Municipality of Portland

				<b>CONDITION RATINGS</b>		
<b>TOWN1:</b>	Portland	<b>TOWN2</b>	No town 2	<b>SUBSTRUCTURE CONDITION</b>	7	Good
<b>BRIDGE NO.:</b>	6299	<b>MAINT REGION</b>	Southern	<b>SUPERSTRUCTURE CONDITION</b>	7	Good
<b>LOCATION:</b>	2 MI N TOWNLINE	<b>YEAR BUILT</b>	1973	<b>DECK CONDITION</b>	7	Good
<b>BRIDGE NAME</b>	PREBLE STREET	<b>SPAN MATERIAL</b>	1 Steel	<b>CHANNEL CONDITION:</b>	6	Satisfactory
<b>OWNER:</b>	1 State DOT	<b>SPAN TYPE:</b>	1 Girder	<b>CULVERT CONDITION:</b>	N	Not Applicable
<b>MAINTAINER</b>	1 State DOT	<b>NUMBER OF MAIN SPANS:</b>	1	<b>APPROACH CONDITION:</b>	7	Good
<b>FEATURE ON:</b>	I-295	<b>STRUCTURE LENGTH IN FEET</b>	116	<b>DATE OF INSPECTION:</b>	1/8/2010	
<b>FEATURE UNDER</b>	PREBLE STREET EXTENS			<b>FEDERAL SUFFICIENCY RATING</b>	98	
<b>ROAD INV NO:</b>	000000295X	<b>POSTING STATUS:</b>	3 Posted			
<b>ROUTE NO:</b>	295	<b>POSTING TYPE:</b>	3 Underclearance Limit			
<b>ROAD WIDTH</b>	102	<b>FEET</b>				
<b>CLASS:</b>	BRIDGE ON STATE HIGHWAY		<b>FEDERAL BRIDGE INDICATOR:</b>	Y		

## Structures in the Municipality of Portland

				<b>CONDITION RATINGS</b>	
<b>TOWN1:</b>	Portland	<b>TOWN2</b>	Falmouth	<b>SUBSTRUCTURE CONDITION</b>	4      Poor
<b>BRIDGE NO.:</b>	2515	<b>MAINT REGION</b>	Southern	<b>SUPERSTRUCTURE CONDITION</b>	4      Poor
<b>LOCATION:</b>	FALMOUTH-PORTLAND	<b>YEAR BUILT</b>	1943	<b>DECK CONDITION</b>	7      Good
<b>BRIDGE NAME</b>	MARTIN POINT	<b>SPAN MATERIAL</b>	1 Steel	<b>CHANNEL CONDITION:</b>	7      Good
<b>OWNER:</b>	1 State DOT	<b>SPAN TYPE:</b>	1 Girder	<b>CULVERT CONDITION:</b>	N      Not Applicable
<b>MAINTAINER</b>	1 State DOT	<b>NUMBER OF MAIN SPANS:</b>	1	<b>APPROACH CONDITION:</b>	7      Good
<b>FEATURE ON:</b>	RTE 1	<b>STRUCTURE LENGTH IN FEET</b>	1403	<b>DATE OF INSPECTION:</b>	1/11/2010
<b>FEATURE UNDER</b>	PRESUMPCOT*RIVER	<b>FEDERAL SUFFICIENCY RATING</b>			
		34.5			
<b>ROAD INV NO:</b>	000000001X	<b>POSTING STATUS:</b>	1 Open		
<b>ROUTE NO:</b>	1	<b>POSTING TYPE:</b>	0 None needed		
<b>ROAD WIDTH</b>	44	<b>FEET</b>			
<b>CLASS:</b>	BRIDGE ON STATE HIGHWAY	<b>FEDERAL BRIDGE INDICATOR:</b>	Y		

## Structures in the Municipality of Portland

				CONDITION RATINGS	
<b>TOWN1:</b>	Portland	<b>TOWN2</b>	No town 2	<b>SUBSTRUCTURE CONDITION</b>	7 <span style="border: 1px solid black; padding: 2px 10px;">Good</span>
<b>BRIDGE NO.:</b>	6291	<b>MAINT REGION</b>	Southern	<b>SUPERSTRUCTURE CONDITION</b>	7 <span style="border: 1px solid black; padding: 2px 10px;">Good</span>
<b>LOCATION:</b>	0.5 MI N TOWNLINE	<b>YEAR BUILT</b>	1974	<b>DECK CONDITION</b>	7 <span style="border: 1px solid black; padding: 2px 10px;">Good</span>
<b>BRIDGE NAME</b>	PTRR(FORERIVER)	<b>SPAN MATERIAL</b>	1 Steel	<b>CHANNEL CONDITION:</b>	6 <span style="border: 1px solid black; padding: 2px 10px;">Satisfactory</span>
<b>OWNER:</b>	1 State DOT	<b>SPAN TYPE:</b>	1 Girder	<b>CULVERT CONDITION:</b>	N <span style="border: 1px solid black; padding: 2px 10px;">Not Applicable</span>
<b>MAINTAINER</b>	1 State DOT	<b>NUMBER OF MAIN SPANS:</b>	3	<b>APPROACH CONDITION:</b>	7 <span style="border: 1px solid black; padding: 2px 10px;">Good</span>
<b>FEATURE ON:</b>	I-295	<b>STRUCTURE LENGTH IN FEET</b>	155	<b>DATE OF INSPECTION:</b>	1/12/2010
<b>FEATURE UNDER</b>	PTRR			<b>FEDERAL SUFFICIENCY RATING</b>	97
<b>ROAD INV NO:</b>	000000295X	<b>POSTING STATUS:</b>	1 Open		
<b>ROUTE NO:</b>	295	<b>POSTING TYPE:</b>	0 None needed		
<b>ROAD WIDTH</b>	78 <b>FEET</b>				
<b>CLASS:</b>	BRIDGE ON STATE HIGHWAY	<b>FEDERAL BRIDGE INDICATOR:</b>	Y		

## Structures in the Municipality of Portland

				CONDITION RATINGS	
<b>TOWN1:</b>	Portland	<b>TOWN2</b>	No town 2	<b>SUBSTRUCTURE CONDITION</b>	7      Good
<b>BRIDGE NO.:</b>	6292	<b>MAINT REGION</b>	Southern	<b>SUPERSTRUCTURE CONDITION</b>	7      Good
<b>LOCATION:</b>	.6 MI N TOWNLINE	<b>YEAR BUILT</b>	1974	<b>DECK CONDITION</b>	6      Satisfactory
<b>BRIDGE NAME</b>	I-295 Over Fore River Park	<b>SPAN MATERIAL</b>	1 Steel	<b>CHANNEL CONDITION:</b>	8      Very Good
<b>OWNER:</b>	1 State DOT	<b>SPAN TYPE:</b>	1 Girder	<b>CULVERT CONDITION:</b>	N      Not Applicable
<b>MAINTAINER</b>	1 State DOT	<b>NUMBER OF MAIN SPANS:</b>	2	<b>APPROACH CONDITION:</b>	7      Good
<b>FEATURE ON:</b>	I-295 & TWO RAMPS	<b>STRUCTURE LENGTH IN FEET</b>	166	<b>DATE OF INSPECTION:</b>	12/21/2009
<b>FEATURE UNDER</b>	Fore River Parkway			<b>FEDERAL SUFFICIENCY RATING</b>	98
<b>ROAD INV NO:</b>	000000295X	<b>POSTING STATUS:</b>	1 Open		
<b>ROUTE NO:</b>	295	<b>POSTING TYPE:</b>	0 None needed		
<b>ROAD WIDTH</b>	86				
	<b>FEET</b>				
<b>CLASS:</b>	BRIDGE ON STATE HIGHWAY	<b>FEDERAL BRIDGE INDICATOR:</b>	Y		

## Structures in the Municipality of Portland

				CONDITION RATINGS	
<b>TOWN1:</b>	Portland	<b>TOWN2</b>	No town 2	<b>SUBSTRUCTURE CONDITION</b>	8      Very Good
<b>BRIDGE NO.:</b>	6294	<b>MAINT REGION</b>	Southern	<b>SUPERSTRUCTURE CONDITION</b>	7      Good
<b>LOCATION:</b>	EXIT 5	<b>YEAR BUILT</b>	1973	<b>DECK CONDITION</b>	7      Good
<b>BRIDGE NAME</b>	CONGRESS & PARK STR	<b>SPAN MATERIAL</b>	1 Steel	<b>CHANNEL CONDITION:</b>	8      Very Good
<b>OWNER:</b>	1 State DOT	<b>SPAN TYPE:</b>	1 Girder	<b>CULVERT CONDITION:</b>	N      Not Applicable
<b>MAINTAINER</b>	1 State DOT	<b>NUMBER OF MAIN SPANS:</b>	2	<b>APPROACH CONDITION:</b>	7      Good
<b>FEATURE ON:</b>	I295	<b>STRUCTURE LENGTH IN FEET</b>	206	<b>DATE OF INSPECTION:</b>	1/12/2010
<b>FEATURE UNDER</b>	CONGRESS&PARK STRE			<b>FEDERAL SUFFICIENCY RATING</b>	97.6
<b>ROAD INV NO:</b>	000000295X	<b>POSTING STATUS:</b>	1 Open		
<b>ROUTE NO:</b>	295	<b>POSTING TYPE:</b>	0 None needed		
<b>ROAD WIDTH</b>	92				
	<b>FEET</b>				
<b>CLASS:</b>	BRIDGE ON STATE HIGHWAY	<b>FEDERAL BRIDGE INDICATOR:</b>	Y		

## Structures in the Municipality of Portland

				<b>CONDITION RATINGS</b>	
<b>TOWN1:</b>	Portland	<b>TOWN2</b>	No town 2	<b>SUBSTRUCTURE CONDITION</b>	6 Satisfactory
<b>BRIDGE NO.:</b>	6295	<b>MAINT REGION</b>	Southern	<b>SUPERSTRUCTURE CONDITION</b>	8 Very Good
<b>LOCATION:</b>	1 MI N TOWNLINE	<b>YEAR BUILT</b>	1973	<b>DECK CONDITION</b>	7 Good
<b>BRIDGE NAME</b>	ST JAMES STREET	<b>SPAN MATERIAL</b>	1 Steel	<b>CHANNEL CONDITION:</b>	7 Good
<b>OWNER:</b>	1 State DOT	<b>SPAN TYPE:</b>	1 Girder	<b>CULVERT CONDITION:</b>	N Not Applicable
<b>MAINTAINER</b>	1 State DOT	<b>NUMBER OF MAIN SPANS:</b>	1	<b>APPROACH CONDITION:</b>	7 Good
<b>FEATURE ON:</b>	I-295 & NB ON RAMP	<b>STRUCTURE LENGTH IN FEET</b>	113	<b>DATE OF INSPECTION:</b>	1/8/2010
<b>FEATURE UNDER</b>	ST JAMES STREET	<b>FEDERAL SUFFICIENCY RATING</b>			
<b>ROAD INV NO:</b>	000000295X	<b>POSTING STATUS:</b>	1 Open		
<b>ROUTE NO:</b>	295	<b>POSTING TYPE:</b>	0 None needed		
<b>ROAD WIDTH</b>	98	<b>FEET</b>			
<b>CLASS:</b>	BRIDGE ON STATE HIGHWAY	<b>FEDERAL BRIDGE INDICATOR:</b>	Y		

## Structures in the Municipality of Portland

				<b>CONDITION RATINGS</b>	
<b>TOWN1:</b>	Portland	<b>TOWN2</b>	No town 2	<b>SUBSTRUCTURE CONDITION</b>	7      Good
<b>BRIDGE NO.:</b>	6296	<b>MAINT REGION</b>	Southern	<b>SUPERSTRUCTURE CONDITION</b>	7      Good
<b>LOCATION:</b>	1 MI N TOWNLINE	<b>YEAR BUILT</b>	1972	<b>DECK CONDITION</b>	7      Good
<b>BRIDGE NAME</b>	PTRR (ST JOHN)	<b>SPAN MATERIAL</b>	1 Steel	<b>CHANNEL CONDITION:</b>	8      Very Good
<b>OWNER:</b>	1 State DOT	<b>SPAN TYPE:</b>	1 Girder	<b>CULVERT CONDITION:</b>	N      Not Applicable
<b>MAINTAINER</b>	1 State DOT	<b>NUMBER OF MAIN SPANS:</b>	1	<b>APPROACH CONDITION:</b>	6      Satisfactory
<b>FEATURE ON:</b>	I-295	<b>STRUCTURE LENGTH IN FEET</b>	115	<b>DATE OF INSPECTION:</b>	1/12/2010
<b>FEATURE UNDER</b>	PTRR	<b>FEDERAL SUFFICIENCY RATING</b>			
<b>ROAD INV NO:</b>	000000295X	<b>POSTING STATUS:</b>	1 Open		
<b>ROUTE NO:</b>	295	<b>POSTING TYPE:</b>	0 None needed		
<b>ROAD WIDTH</b>	114	<b>FEET</b>			
<b>CLASS:</b>	BRIDGE ON STATE HIGHWAY	<b>FEDERAL BRIDGE INDICATOR:</b>	Y		

## Structures in the Municipality of Portland

				CONDITION RATINGS	
<b>TOWN1:</b>	Portland	<b>TOWN2</b>	No town 2	<b>SUBSTRUCTURE CONDITION</b>	7      Good
<b>BRIDGE NO.:</b>	6280	<b>MAINT REGION</b>	Southern	<b>SUPERSTRUCTURE CONDITION</b>	7      Good
<b>LOCATION:</b>	.5 MI W US1	<b>YEAR BUILT</b>	1971	<b>DECK CONDITION</b>	7      Good
<b>BRIDGE NAME</b>	DEERING AVENUE BRID	<b>SPAN MATERIAL</b>	1 Steel	<b>CHANNEL CONDITION:</b>	8      Very Good
<b>OWNER:</b>	1 State DOT	<b>SPAN TYPE:</b>	1 Girder	<b>CULVERT CONDITION:</b>	N      Not Applicable
<b>MAINTAINER</b>	1 State DOT	<b>NUMBER OF MAIN SPANS:</b>	3	<b>APPROACH CONDITION:</b>	7      Good
<b>FEATURE ON:</b>	ROUTE 25 (DEERING	<b>STRUCTURE LENGTH IN FEET</b>	247	<b>DATE OF INSPECTION:</b>	12/30/2009
<b>FEATURE UNDER</b>	I-295 + PTRR			<b>FEDERAL SUFFICIENCY RATING</b>	92.2
<b>ROAD INV NO:</b>	000000025X	<b>POSTING STATUS:</b>	1 Open		
<b>ROUTE NO:</b>	25	<b>POSTING TYPE:</b>	0 None needed		
<b>ROAD WIDTH</b>	54				
	<b>FEET</b>				
<b>CLASS:</b>	BRIDGE ON TOWN WAY OR STATE AID ROAD	<b>FEDERAL BRIDGE INDICATOR:</b>	Y		

## Structures in the Municipality of Portland

				CONDITION RATINGS	
<b>TOWN1:</b>	Portland	<b>TOWN2</b>	No town 2	<b>SUBSTRUCTURE CONDITION</b>	6 Satisfactory
<b>BRIDGE NO.:</b>	6298	<b>MAINT REGION</b>	Southern	<b>SUPERSTRUCTURE CONDITION</b>	7 Good
<b>LOCATION:</b>	EXIT 6	<b>YEAR BUILT</b>	1973	<b>DECK CONDITION</b>	7 Good
<b>BRIDGE NAME</b>	FOREST AVE	<b>SPAN MATERIAL</b>	1 Steel	<b>CHANNEL CONDITION:</b>	8 Very Good
<b>OWNER:</b>	1 State DOT	<b>SPAN TYPE:</b>	1 Girder	<b>CULVERT CONDITION:</b>	N Not Applicable
<b>MAINTAINER</b>	1 State DOT	<b>NUMBER OF MAIN SPANS:</b>	1	<b>APPROACH CONDITION:</b>	7 Good
<b>FEATURE ON:</b>	I295	<b>STRUCTURE LENGTH IN FEET</b>	130	<b>DATE OF INSPECTION:</b>	12/30/2009
<b>FEATURE UNDER</b>	US RTE1(FOREST AVE)			<b>FEDERAL SUFFICIENCY RATING</b>	97
<b>ROAD INV NO:</b>	000000295X	<b>POSTING STATUS:</b>	3 Posted		
<b>ROUTE NO:</b>	295	<b>POSTING TYPE:</b>	3 Underclearance Limit		
<b>ROAD WIDTH</b>	96 FEET				
<b>CLASS:</b>	BRIDGE ON STATE HIGHWAY	<b>FEDERAL BRIDGE INDICATOR:</b>	Y		

## Structures in the Municipality of Portland

			<b>CONDITION RATINGS</b>	
<b>TOWN1:</b>	Portland	<b>TOWN2</b>	No town 2	<b>SUBSTRUCTURE CONDITION</b> <span style="border: 1px solid black; padding: 2px 10px;">7</span> <span style="border: 1px solid black; padding: 2px 10px;">Good</span>
<b>BRIDGE NO.:</b>	5933	<b>MAINT REGION</b>	Southern	<b>SUPERSTRUCTURE CONDITION</b> <span style="border: 1px solid black; padding: 2px 10px;">6</span> <span style="border: 1px solid black; padding: 2px 10px;">Satisfactory</span>
<b>LOCATION:</b>	I-295 OVER US1	<b>YEAR BUILT</b>	1961	<b>DECK CONDITION</b> <span style="border: 1px solid black; padding: 2px 10px;">5</span> <span style="border: 1px solid black; padding: 2px 10px;">Fair</span>
<b>BRIDGE NAME</b>	I-295 OVER VERANDA S	<b>SPAN MATERIAL</b>	1 Steel	<b>CHANNEL CONDITION:</b> <span style="border: 1px solid black; padding: 2px 10px;">6</span> <span style="border: 1px solid black; padding: 2px 10px;">Satisfactory</span>
<b>OWNER:</b>	1 State DOT	<b>SPAN TYPE:</b>	1 Girder	<b>CULVERT CONDITION:</b> <span style="border: 1px solid black; padding: 2px 10px;">N</span> <span style="border: 1px solid black; padding: 2px 10px;">Not Applicable</span>
<b>MAINTAINER</b>	1 State DOT	<b>NUMBER OF MAIN SPANS:</b>	3	<b>APPROACH CONDITION:</b> <span style="border: 1px solid black; padding: 2px 10px;">6</span> <span style="border: 1px solid black; padding: 2px 10px;">Satisfactory</span>
<b>FEATURE ON:</b>	I 295	<b>STRUCTURE LENGTH IN FEET</b>	200	<b>DATE OF INSPECTION:</b> <span style="border: 1px solid black; padding: 2px 10px;">12/21/2009</span>
<b>FEATURE UNDER</b>	VERANDA ST & US 1	<b>FEDERAL SUFFICIENCY RATING</b> <span style="border: 1px solid black; padding: 2px 10px;">95</span>		
<b>ROAD INV NO:</b>	000000295X	<b>POSTING STATUS:</b>	1 Open	
<b>ROUTE NO:</b>	295	<b>POSTING TYPE:</b>	0 None needed	
<b>ROAD WIDTH</b>	61	<b>FEET</b>		
<b>CLASS:</b>	BRIDGE ON STATE HIGHWAY	<b>FEDERAL BRIDGE INDICATOR:</b>	Y	

## Structures in the Municipality of Portland

				CONDITION RATINGS	
<b>TOWN1:</b>	Portland	<b>TOWN2</b>	No town 2	<b>SUBSTRUCTURE CONDITION</b>	7      Good
<b>BRIDGE NO.:</b>	6300	<b>MAINT REGION</b>	Southern	<b>SUPERSTRUCTURE CONDITION</b>	7      Good
<b>LOCATION:</b>	2.2 MI N TOWNLINE	<b>YEAR BUILT</b>	1974	<b>DECK CONDITION</b>	7      Good
<b>BRIDGE NAME</b>	FRANKLIN ST	<b>SPAN MATERIAL</b>	1 Steel	<b>CHANNEL CONDITION:</b>	7      Good
<b>OWNER:</b>	1 State DOT	<b>SPAN TYPE:</b>	1 Girder	<b>CULVERT CONDITION:</b>	N      Not Applicable
<b>MAINTAINER</b>	1 State DOT	<b>NUMBER OF MAIN SPANS:</b>	1	<b>APPROACH CONDITION:</b>	7      Good
<b>FEATURE ON:</b>	I-295	<b>STRUCTURE LENGTH IN FEET</b>	116	<b>DATE OF INSPECTION:</b>	1/7/2010
<b>FEATURE UNDER</b>	FRANKLIN STREET			<b>FEDERAL SUFFICIENCY RATING</b>	98
<b>ROAD INV NO:</b>	000000295X	<b>POSTING STATUS:</b>	1 Open		
<b>ROUTE NO:</b>	295	<b>POSTING TYPE:</b>	0 None needed		
<b>ROAD WIDTH</b>	83				
	<b>FEET</b>				
<b>CLASS:</b>	BRIDGE ON STATE HIGHWAY	<b>FEDERAL BRIDGE INDICATOR:</b>	Y		

## Structures in the Municipality of Portland

				CONDITION RATINGS	
<b>TOWN1:</b>	Portland	<b>TOWN2</b>	No town 2	<b>SUBSTRUCTURE CONDITION</b>	6 Satisfactory
<b>BRIDGE NO.:</b>	6348	<b>MAINT REGION</b>	Southern	<b>SUPERSTRUCTURE CONDITION</b>	7 Good
<b>LOCATION:</b>	Forest City Landing	<b>YEAR BUILT</b>	1993	<b>DECK CONDITION</b>	7 Good
<b>BRIDGE NAME</b>	Peaks Island Transfer	<b>SPAN MATERIAL</b>	1 Steel	<b>CHANNEL CONDITION:</b>	7 Good
<b>OWNER:</b>	1 State DOT	<b>SPAN TYPE:</b>	2 Girder - floor beam	<b>CULVERT CONDITION:</b>	-
<b>MAINTAINER</b>	1 State DOT	<b>NUMBER OF MAIN SPANS:</b>	2	<b>APPROACH CONDITION:</b>	
<b>FEATURE ON:</b>	Town Way	<b>STRUCTURE LENGTH IN FEET</b>	105	<b>DATE OF INSPECTION:</b>	1/26/2010
<b>FEATURE UNDER</b>	Casco Bay/Atlantic Ocean			<b>FEDERAL SUFFICIENCY RATING</b>	100
<b>ROAD INV NO:</b>	0000560958	<b>POSTING STATUS:</b>	1 Open		
<b>ROUTE NO:</b>	0	<b>POSTING TYPE:</b>	0 None needed		
<b>ROAD WIDTH</b>	-3				
	<b>FEET</b>				
<b>CLASS:</b>		<b>FEDERAL BRIDGE INDICATOR:</b>	Y		

## Structures in the Municipality of Portland

				CONDITION RATINGS	
<b>TOWN1:</b>	Portland	<b>TOWN2</b>	No town 2	<b>SUBSTRUCTURE CONDITION</b>	N      Not Applicable
<b>BRIDGE NO.:</b>	6413	<b>MAINT REGION</b>	Southern	<b>SUPERSTRUCTURE CONDITION</b>	N      Not Applicable
<b>LOCATION:</b>	.2 N RT 25	<b>YEAR BUILT</b>	1998	<b>DECK CONDITION</b>	N      Not Applicable
<b>BRIDGE NAME</b>	DENNETT STREET	<b>SPAN MATERIAL</b>	7 Precast Concrete	<b>CHANNEL CONDITION:</b>	8      Very Good
<b>OWNER:</b>	4 Municipal	<b>SPAN TYPE:</b>	6 Arch	<b>CULVERT CONDITION:</b>	8      Very Good
<b>MAINTAINER</b>	4 Municipal	<b>NUMBER OF MAIN SPANS:</b>	1	<b>APPROACH CONDITION:</b>	7      Good
<b>FEATURE ON:</b>	DENNETT STREET	<b>STRUCTURE LENGTH IN FEET</b>	16	<b>DATE OF INSPECTION:</b>	1/26/2010
<b>FEATURE UNDER</b>	CAPISIC BROOK			<b>FEDERAL SUFFICIENCY RATING</b>	99
<b>ROAD INV NO:</b>	0000560211	<b>POSTING STATUS:</b>	1 Open		
<b>ROUTE NO:</b>	0	<b>POSTING TYPE:</b>	0 None needed		
<b>ROAD WIDTH</b>	0				
	<b>FEET</b>				
<b>CLASS:</b>	MINOR SPAN ON TOWN WAY	<b>FEDERAL BRIDGE INDICATOR:</b>	N		

## Structures in the Municipality of Portland

				CONDITION RATINGS	
<b>TOWN1:</b>	Portland	<b>TOWN2</b>	No town 2	<b>SUBSTRUCTURE CONDITION</b>	N      Not Applicable
<b>BRIDGE NO.:</b>	6414	<b>MAINT REGION</b>	Southern	<b>SUPERSTRUCTURE CONDITION</b>	N      Not Applicable
<b>LOCATION:</b>	.1 E HARMON ROAD	<b>YEAR BUILT</b>	1998	<b>DECK CONDITION</b>	N      Not Applicable
<b>BRIDGE NAME</b>	VIOLETTE AVENUE	<b>SPAN MATERIAL</b>	7 Precast Concrete	<b>CHANNEL CONDITION:</b>	7      Good
<b>OWNER:</b>	4 Municipal	<b>SPAN TYPE:</b>	6 Arch	<b>CULVERT CONDITION:</b>	8      Very Good
<b>MAINTAINER</b>	4 Municipal	<b>NUMBER OF MAIN SPANS:</b>	1	<b>APPROACH CONDITION:</b>	7      Good
<b>FEATURE ON:</b>	VIOLETTE AVENUE	<b>STRUCTURE LENGTH IN FEET</b>	16	<b>DATE OF INSPECTION:</b>	1/26/2010
<b>FEATURE UNDER</b>	CAPISIC BROOK			<b>FEDERAL SUFFICIENCY RATING</b>	93.6
<b>ROAD INV NO:</b>	0000560760	<b>POSTING STATUS:</b>	1 Open		
<b>ROUTE NO:</b>	0	<b>POSTING TYPE:</b>	0 None needed		
<b>ROAD WIDTH</b>	0				
	<b>FEET</b>				
<b>CLASS:</b>	MINOR SPAN ON TOWN WAY	<b>FEDERAL BRIDGE INDICATOR:</b>	N		

## Structures in the Municipality of Portland

				CONDITION RATINGS	
<b>TOWN1:</b>	Portland	<b>TOWN2</b>	No town 2	<b>SUBSTRUCTURE CONDITION</b>	8      Very Good
<b>BRIDGE NO.:</b>	6422	<b>MAINT REGION</b>	Southern	<b>SUPERSTRUCTURE CONDITION</b>	8      Very Good
<b>LOCATION:</b>	.3 east of I-295	<b>YEAR BUILT</b>	2005	<b>DECK CONDITION</b>	8      Very Good
<b>BRIDGE NAME</b>	Connector Road over Future	<b>SPAN MATERIAL</b>	1 Steel	<b>CHANNEL CONDITION:</b>	
<b>OWNER:</b>	1 State DOT	<b>SPAN TYPE:</b>	1 Girder	<b>CULVERT CONDITION:</b>	N      Not Applicable
<b>MAINTAINER</b>	1 State DOT	<b>NUMBER OF MAIN SPANS:</b>	1	<b>APPROACH CONDITION:</b>	5      Fair
<b>FEATURE ON:</b>	Connector Road	<b>STRUCTURE LENGTH IN FEET</b>	63	<b>DATE OF INSPECTION:</b>	2/10/2010
<b>FEATURE UNDER</b>	Future WYE Railroad/ ped			<b>FEDERAL SUFFICIENCY RATING</b>	100
<b>ROAD INV NO:</b>	000000001A	<b>POSTING STATUS:</b>	1 Open		
<b>ROUTE NO:</b>	1	<b>POSTING TYPE:</b>	0 None needed		
<b>ROAD WIDTH</b>	24				
	<b>FEET</b>				
<b>CLASS:</b>	BRIDGE ON STATE HIGHWAY	<b>FEDERAL BRIDGE INDICATOR:</b>	Y		

## Structures in the Municipality of Portland

				CONDITION RATINGS	
<b>TOWN1:</b>	Portland	<b>TOWN2</b>	No town 2	<b>SUBSTRUCTURE CONDITION</b>	8      Very Good
<b>BRIDGE NO.:</b>	6423	<b>MAINT REGION</b>	Southern	<b>SUPERSTRUCTURE CONDITION</b>	8      Very Good
<b>LOCATION:</b>	.3 mi east of I-295	<b>YEAR BUILT</b>	2005	<b>DECK CONDITION</b>	8      Very Good
<b>BRIDGE NAME</b>	Connector Road over Moun	<b>SPAN MATERIAL</b>	1 Steel	<b>CHANNEL CONDITION:</b>	
<b>OWNER:</b>	1 State DOT	<b>SPAN TYPE:</b>	1 Girder	<b>CULVERT CONDITION:</b>	N      Not Applicable
<b>MAINTAINER</b>	1 State DOT	<b>NUMBER OF MAIN SPANS:</b>	1	<b>APPROACH CONDITION:</b>	5      Fair
<b>FEATURE ON:</b>	Connector Rod	<b>STRUCTURE LENGTH IN FEET</b>	95	<b>DATE OF INSPECTION:</b>	2/10/2010
<b>FEATURE UNDER</b>	Mountain division RR			<b>FEDERAL SUFFICIENCY RATING</b>	96
<b>ROAD INV NO:</b>	000000001A	<b>POSTING STATUS:</b>	1 Open		
<b>ROUTE NO:</b>	1	<b>POSTING TYPE:</b>	0 None needed		
<b>ROAD WIDTH</b>	30				
	<b>FEET</b>				
<b>CLASS:</b>	BRIDGE ON STATE HIGHWAY	<b>FEDERAL BRIDGE INDICATOR:</b>	Y		

## Structures in the Municipality of Portland

				CONDITION RATINGS	
<b>TOWN1:</b>	<input type="text" value="Portland"/>	<b>TOWN2</b>	<input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION</b>	<input type="text" value="7"/> <input type="text" value="Good"/>
<b>BRIDGE NO.:</b>	<input type="text" value="6297"/>	<b>MAINT REGION</b>	<input type="text" value="Southern"/>	<b>SUPERSTRUCTURE CONDITION</b>	<input type="text" value="8"/> <input type="text" value="Very Good"/>
<b>LOCATION:</b>	<input type="text" value="1 MI N TOWNLINE"/>	<b>YEAR BUILT</b>	<input type="text" value="1972"/>	<b>DECK CONDITION</b>	<input type="text" value="7"/> <input type="text" value="Good"/>
<b>BRIDGE NAME</b>	<input type="text" value="ST JOHN STREET"/>	<b>SPAN MATERIAL</b>	<input type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b>	<input type="text" value="7"/> <input type="text" value="Good"/>
<b>OWNER:</b>	<input type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b>	<input type="text" value="1 Girder"/>	<b>CULVERT CONDITION:</b>	<input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER</b>	<input type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b>	<input type="text" value="1"/>	<b>APPROACH CONDITION:</b>	<input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>FEATURE ON:</b>	<input type="text" value="I-295"/>	<b>STRUCTURE LENGTH IN FEET</b>	<input type="text" value="116"/>	<b>DATE OF INSPECTION:</b>	<input type="text" value="1/8/2010"/>
<b>FEATURE UNDER</b>	<input type="text" value="ST JOHN STREET"/>			<b>FEDERAL SUFFICIENCY RATING</b>	<input type="text" value="96"/>
<b>ROAD INV NO:</b>	<input type="text" value="000000295X"/>	<b>POSTING STATUS:</b>	<input type="text" value="3 Posted"/>		
<b>ROUTE NO:</b>	<input type="text" value="295"/>	<b>POSTING TYPE:</b>	<input type="text" value="3 Underclearance Limit"/>		
<b>ROAD WIDTH</b>	<input type="text" value="98"/> <b>FEET</b>				
<b>CLASS:</b>	<input type="text" value="BRIDGE ON STATE HIGHWAY"/>	<b>FEDERAL BRIDGE INDICATOR:</b>	<input type="text" value="Y"/>		

## Structures in the Municipality of Portland

				CONDITION RATINGS	
<b>TOWN1:</b>	Portland	<b>TOWN2</b>	No town 2	<b>SUBSTRUCTURE CONDITION</b>	N      Not Applicable
<b>BRIDGE NO.:</b>	5182	<b>MAINT REGION</b>	Southern	<b>SUPERSTRUCTURE CONDITION</b>	N      Not Applicable
<b>LOCATION:</b>	AT INTER. MAYER STRE	<b>YEAR BUILT</b>	2000	<b>DECK CONDITION</b>	N      Not Applicable
<b>BRIDGE NAME</b>	CAPISIC	<b>SPAN MATERIAL</b>	7 Precast Concrete	<b>CHANNEL CONDITION:</b>	8      Very Good
<b>OWNER:</b>	1 State DOT	<b>SPAN TYPE:</b>	4 Culvert	<b>CULVERT CONDITION:</b>	9      Excellent
<b>MAINTAINER</b>	1 State DOT	<b>NUMBER OF MAIN SPANS:</b>	2	<b>APPROACH CONDITION:</b>	8      Very Good
<b>FEATURE ON:</b>	25	<b>STRUCTURE LENGTH IN FEET</b>	23	<b>DATE OF INSPECTION:</b>	1/7/2009
<b>FEATURE UNDER</b>	CAPISIC BROOK			<b>FEDERAL SUFFICIENCY RATING</b>	71.8
<b>ROAD INV NO:</b>	000000025X	<b>POSTING STATUS:</b>	1 Open		
<b>ROUTE NO:</b>	25	<b>POSTING TYPE:</b>	0 None needed		
<b>ROAD WIDTH</b>	0				
	<b>FEET</b>				
<b>CLASS:</b>	BRIDGE ON STATE HIGHWAY	<b>FEDERAL BRIDGE INDICATOR:</b>	Y		

## Structures in the Municipality of Portland

			CONDITION RATINGS	
<b>TOWN1:</b>	Portland	<b>TOWN2</b>	No town 2	<b>SUBSTRUCTURE CONDITION</b> <span style="border: 1px solid black; padding: 2px 10px;">9</span> <span style="border: 1px solid black; padding: 2px 10px;">Excellent</span>
<b>BRIDGE NO.:</b>	6424	<b>MAINT REGION</b>	Southern	<b>SUPERSTRUCTURE CONDITION</b> <span style="border: 1px solid black; padding: 2px 10px;">9</span> <span style="border: 1px solid black; padding: 2px 10px;">Excellent</span>
<b>LOCATION:</b>	.5 miles East of I-295	<b>YEAR BUILT</b>	2005	<b>DECK CONDITION</b> <span style="border: 1px solid black; padding: 2px 10px;">9</span> <span style="border: 1px solid black; padding: 2px 10px;">Excellent</span>
<b>BRIDGE NAME</b>	Mercy Access RD\GRS	<b>SPAN MATERIAL</b>	1 Steel	<b>CHANNEL CONDITION:</b> <span style="border: 1px solid black; padding: 2px 10px;"></span> <span style="border: 1px solid black; padding: 2px 10px;"></span>
<b>OWNER:</b>	1 State DOT	<b>SPAN TYPE:</b>	1 Girder	<b>CULVERT CONDITION:</b> <span style="border: 1px solid black; padding: 2px 10px;">N</span> <span style="border: 1px solid black; padding: 2px 10px;">Not Applicable</span>
<b>MAINTAINER</b>	1 State DOT	<b>NUMBER OF MAIN SPANS:</b>	4	<b>APPROACH CONDITION:</b> <span style="border: 1px solid black; padding: 2px 10px;">8</span> <span style="border: 1px solid black; padding: 2px 10px;">Very Good</span>
<b>FEATURE ON:</b>	Connector Road	<b>STRUCTURE LENGTH IN FEET</b>	378	<b>DATE OF INSPECTION:</b> <span style="border: 1px solid black; padding: 2px 10px;">12/23/2009</span>
<b>FEATURE UNDER</b>	Mercy Access Rd. GRS			<b>FEDERAL SUFFICIENCY RATING</b> <span style="border: 1px solid black; padding: 2px 10px;">100</span>
<b>ROAD INV NO:</b>	000000001A	<b>POSTING STATUS:</b>	1 Open	
<b>ROUTE NO:</b>	1	<b>POSTING TYPE:</b>	0 None needed	
<b>ROAD WIDTH</b>	47			<b>FEET</b>
<b>CLASS:</b>	BRIDGE ON STATE HIGHWAY	<b>FEDERAL BRIDGE INDICATOR:</b>	Y	

## Structures in the Municipality of Portland

				CONDITION RATINGS	
<b>TOWN1:</b>	Portland	<b>TOWN2</b>	No town 2	<b>SUBSTRUCTURE CONDITION</b>	6 Satisfactory
<b>BRIDGE NO.:</b>	2816	<b>MAINT REGION</b>	Southern	<b>SUPERSTRUCTURE CONDITION</b>	7 Good
<b>LOCATION:</b>	0.6 MI NE OF SW JCT 9&	<b>YEAR BUILT</b>	1989	<b>DECK CONDITION</b>	7 Good
<b>BRIDGE NAME</b>	STROUDWATER	<b>SPAN MATERIAL</b>	2 Concrete	<b>CHANNEL CONDITION:</b>	7 Good
<b>OWNER:</b>	1 State DOT	<b>SPAN TYPE:</b>	7 Rigid Frame	<b>CULVERT CONDITION:</b>	N Not Applicable
<b>MAINTAINER</b>	1 State DOT	<b>NUMBER OF MAIN SPANS:</b>	1	<b>APPROACH CONDITION:</b>	7 Good
<b>FEATURE ON:</b>	ROUTES 9 & 22	<b>STRUCTURE LENGTH IN FEET</b>	43	<b>DATE OF INSPECTION:</b>	11/24/2009
<b>FEATURE UNDER</b>	STROUDWATER RIVER			<b>FEDERAL SUFFICIENCY RATING</b>	71.5
<b>ROAD INV NO:</b>	000000009X	<b>POSTING STATUS:</b>	1 Open		
<b>ROUTE NO:</b>	9	<b>POSTING TYPE:</b>	0 None needed		
<b>ROAD WIDTH</b>	53				
	<b>FEET</b>				
<b>CLASS:</b>	BRIDGE ON TOWN WAY OR STATE AID ROAD	<b>FEDERAL BRIDGE INDICATOR:</b>	Y		

## Structures in the Municipality of Portland

				<b>CONDITION RATINGS</b>	
<b>TOWN1:</b>	Portland	<b>TOWN2</b>	Westbrook	<b>SUBSTRUCTURE CONDITION</b>	8      Very Good
<b>BRIDGE NO.:</b>	2932	<b>MAINT REGION</b>	Southern	<b>SUPERSTRUCTURE CONDITION</b>	8      Very Good
<b>LOCATION:</b>	PORTLAND-WESTBROO	<b>YEAR BUILT</b>	1994	<b>DECK CONDITION</b>	7      Good
<b>BRIDGE NAME</b>	PRIDES	<b>SPAN MATERIAL</b>	1 Steel	<b>CHANNEL CONDITION:</b>	5      Fair
<b>OWNER:</b>	1 State DOT	<b>SPAN TYPE:</b>	1 Girder	<b>CULVERT CONDITION:</b>	N      Not Applicable
<b>MAINTAINER</b>	1 State DOT	<b>NUMBER OF MAIN SPANS:</b>	2	<b>APPROACH CONDITION:</b>	7      Good
<b>FEATURE ON:</b>	ROUTE 302	<b>STRUCTURE LENGTH IN FEET</b>	177	<b>DATE OF INSPECTION:</b>	12/8/2009
<b>FEATURE UNDER</b>	PRESUMPCOT RIVER	<b>FEDERAL SUFFICIENCY RATING</b>			
<b>ROAD INV NO:</b>	000000302X	<b>POSTING STATUS:</b>	1 Open		
<b>ROUTE NO:</b>	302	<b>POSTING TYPE:</b>	0 None needed		
<b>ROAD WIDTH</b>	52	<b>FEET</b>			
<b>CLASS:</b>	BRIDGE ON STATE HIGHWAY	<b>FEDERAL BRIDGE INDICATOR:</b>	Y		

## Structures in the Municipality of Portland

			CONDITION RATINGS	
<b>TOWN1:</b>	Portland	<b>TOWN2</b>	No town 2	<b>SUBSTRUCTURE CONDITION</b> <span style="border: 1px solid black; padding: 2px 10px;">6</span> <span style="border: 1px solid black; padding: 2px 10px;">Satisfactory</span>
<b>BRIDGE NO.:</b>	3088	<b>MAINT REGION</b>	Southern	<b>SUPERSTRUCTURE CONDITION</b> <span style="border: 1px solid black; padding: 2px 10px;">6</span> <span style="border: 1px solid black; padding: 2px 10px;">Satisfactory</span>
<b>LOCATION:</b>	1.6 MI S TOWNLINE	<b>YEAR BUILT</b>	1960	<b>DECK CONDITION</b> <span style="border: 1px solid black; padding: 2px 10px;">5</span> <span style="border: 1px solid black; padding: 2px 10px;">Fair</span>
<b>BRIDGE NAME</b>	TUKEY	<b>SPAN MATERIAL</b>	1 Steel	<b>CHANNEL CONDITION:</b> <span style="border: 1px solid black; padding: 2px 10px;">6</span> <span style="border: 1px solid black; padding: 2px 10px;">Satisfactory</span>
<b>OWNER:</b>	1 State DOT	<b>SPAN TYPE:</b>	1 Girder	<b>CULVERT CONDITION:</b> <span style="border: 1px solid black; padding: 2px 10px;">N</span> <span style="border: 1px solid black; padding: 2px 10px;">Not Applicable</span>
<b>MAINTAINER</b>	1 State DOT	<b>NUMBER OF MAIN SPANS:</b>	4	<b>APPROACH CONDITION:</b> <span style="border: 1px solid black; padding: 2px 10px;">7</span> <span style="border: 1px solid black; padding: 2px 10px;">Good</span>
<b>FEATURE ON:</b>	I295 & US 1A	<b>STRUCTURE LENGTH IN FEET</b>	505	<b>DATE OF INSPECTION:</b> <span style="border: 1px solid black; padding: 2px 10px;">1/13/2010</span>
<b>FEATURE UNDER</b>	BACK BAY (ATLANTIC O			<b>FEDERAL SUFFICIENCY RATING</b> <span style="border: 1px solid black; padding: 2px 10px;">79.4</span>
<b>ROAD INV NO:</b>	000000295X	<b>POSTING STATUS:</b>	1 Open	
<b>ROUTE NO:</b>	295	<b>POSTING TYPE:</b>	0 None needed	
<b>ROAD WIDTH</b>	96			<b>FEET</b>
<b>CLASS:</b>	BRIDGE ON STATE HIGHWAY	<b>FEDERAL BRIDGE INDICATOR:</b>	Y	

## Structures in the Municipality of Portland

				CONDITION RATINGS	
<b>TOWN1:</b>	Portland	<b>TOWN2</b>	No town 2	<b>SUBSTRUCTURE CONDITION</b>	6 Satisfactory
<b>BRIDGE NO.:</b>	3486	<b>MAINT REGION</b>	Southern	<b>SUPERSTRUCTURE CONDITION</b>	6 Satisfactory
<b>LOCATION:</b>	0.8 MI NE OF SW JCT 9&	<b>YEAR BUILT</b>	1937	<b>DECK CONDITION</b>	6 Satisfactory
<b>BRIDGE NAME</b>	STROUDWATER FORE R	<b>SPAN MATERIAL</b>	2 Concrete	<b>CHANNEL CONDITION:</b>	6 Satisfactory
<b>OWNER:</b>	1 State DOT	<b>SPAN TYPE:</b>	3 Slab	<b>CULVERT CONDITION:</b>	N Not Applicable
<b>MAINTAINER</b>	1 State DOT	<b>NUMBER OF MAIN SPANS:</b>	1	<b>APPROACH CONDITION:</b>	7 Good
<b>FEATURE ON:</b>	ROUTES 9 & 22	<b>STRUCTURE LENGTH IN FEET</b>	29	<b>DATE OF INSPECTION:</b>	11/24/2009
<b>FEATURE UNDER</b>	FORE RIVER			<b>FEDERAL SUFFICIENCY RATING</b>	90.8
<b>ROAD INV NO:</b>	000000009X	<b>POSTING STATUS:</b>	1 Open		
<b>ROUTE NO:</b>	9	<b>POSTING TYPE:</b>	0 None needed		
<b>ROAD WIDTH</b>	53				
	<b>FEET</b>				
<b>CLASS:</b>	BRIDGE ON TOWN WAY OR STATE AID ROAD	<b>FEDERAL BRIDGE INDICATOR:</b>	Y		

## Structures in the Municipality of Portland

				CONDITION RATINGS	
<b>TOWN1:</b>	Portland	<b>TOWN2</b>	No town 2	<b>SUBSTRUCTURE CONDITION</b>	6 Satisfactory
<b>BRIDGE NO.:</b>	3525	<b>MAINT REGION</b>	Southern	<b>SUPERSTRUCTURE CONDITION</b>	5 Fair
<b>LOCATION:</b>	50 FT SW OF US1A CIRC	<b>YEAR BUILT</b>	1939	<b>DECK CONDITION</b>	5 Fair
<b>BRIDGE NAME</b>	DANFORTH ST CROSSIN	<b>SPAN MATERIAL</b>	2 Concrete	<b>CHANNEL CONDITION:</b>	8 Very Good
<b>OWNER:</b>	6 Railroad	<b>SPAN TYPE:</b>	7 Rigid Frame	<b>CULVERT CONDITION:</b>	N Not Applicable
<b>MAINTAINER</b>	1 State DOT	<b>NUMBER OF MAIN SPANS:</b>	1	<b>APPROACH CONDITION:</b>	5 Fair
<b>FEATURE ON:</b>	DANFORTH STREET	<b>STRUCTURE LENGTH IN FEET</b>	43	<b>DATE OF INSPECTION:</b>	1/27/2010
<b>FEATURE UNDER</b>	PTRR			<b>FEDERAL SUFFICIENCY RATING</b>	92
<b>ROAD INV NO:</b>	0003200162	<b>POSTING STATUS:</b>	1 Open		
<b>ROUTE NO:</b>	0	<b>POSTING TYPE:</b>	0 None needed		
<b>ROAD WIDTH</b>	64 FEET				
<b>CLASS:</b>	RAILROAD BRIDGE	<b>FEDERAL BRIDGE INDICATOR:</b>	Y		

## Structures in the Municipality of Portland

				CONDITION RATINGS	
<b>TOWN1:</b>	Portland	<b>TOWN2</b>	No town 2	<b>SUBSTRUCTURE CONDITION</b>	9      Excellent
<b>BRIDGE NO.:</b>	5052	<b>MAINT REGION</b>	Southern	<b>SUPERSTRUCTURE CONDITION</b>	9      Excellent
<b>LOCATION:</b>	.3 MI N WASHINGTON S	<b>YEAR BUILT</b>	2009	<b>DECK CONDITION</b>	9      Excellent
<b>BRIDGE NAME</b>	VERANDA ST. OVERPAS	<b>SPAN MATERIAL</b>	7 Precast Concrete	<b>CHANNEL CONDITION:</b>	8      Very Good
<b>OWNER:</b>	1 State DOT	<b>SPAN TYPE:</b>	3 Slab	<b>CULVERT CONDITION:</b>	N      Not Applicable
<b>MAINTAINER</b>	1 State DOT	<b>NUMBER OF MAIN SPANS:</b>	1	<b>APPROACH CONDITION:</b>	8      Very Good
<b>FEATURE ON:</b>	VERANDA STREET	<b>STRUCTURE LENGTH IN FEET</b>	34	<b>DATE OF INSPECTION:</b>	11/19/2009
<b>FEATURE UNDER</b>	C N R R			<b>FEDERAL SUFFICIENCY RATING</b>	39.7
<b>ROAD INV NO:</b>	0000560753	<b>POSTING STATUS:</b>	1 Open		
<b>ROUTE NO:</b>	0	<b>POSTING TYPE:</b>	0 None needed		
<b>ROAD WIDTH</b>	41				
	<b>FEET</b>				
<b>CLASS:</b>	RAILROAD BRIDGE	<b>FEDERAL BRIDGE INDICATOR:</b>	Y		

## Structures in the Municipality of Portland

				CONDITION RATINGS	
<b>TOWN1:</b>	Portland	<b>TOWN2</b>	No town 2	<b>SUBSTRUCTURE CONDITION</b>	6 Satisfactory
<b>BRIDGE NO.:</b>	2561	<b>MAINT REGION</b>	Southern	<b>SUPERSTRUCTURE CONDITION</b>	7 Good
<b>LOCATION:</b>	0.2 MI SE OF RTES (&22	<b>YEAR BUILT</b>	1983	<b>DECK CONDITION</b>	7 Good
<b>BRIDGE NAME</b>	MILL CREEK	<b>SPAN MATERIAL</b>	2 Concrete	<b>CHANNEL CONDITION:</b>	7 Good
<b>OWNER:</b>	1 State DOT	<b>SPAN TYPE:</b>	6 Arch	<b>CULVERT CONDITION:</b>	N Not Applicable
<b>MAINTAINER</b>	1 State DOT	<b>NUMBER OF MAIN SPANS:</b>	1	<b>APPROACH CONDITION:</b>	7 Good
<b>FEATURE ON:</b>	WESTBROOK STREET	<b>STRUCTURE LENGTH IN FEET</b>	68	<b>DATE OF INSPECTION:</b>	11/24/2009
<b>FEATURE UNDER</b>	STROUDWATER RV			<b>FEDERAL SUFFICIENCY RATING</b>	99.9
<b>ROAD INV NO:</b>	0000560784	<b>POSTING STATUS:</b>	1 Open		
<b>ROUTE NO:</b>	0	<b>POSTING TYPE:</b>	0 None needed		
<b>ROAD WIDTH</b>	36				
	<b>FEET</b>				
<b>CLASS:</b>	BRIDGE ON TOWN WAY OR STATE AID ROAD	<b>FEDERAL BRIDGE INDICATOR:</b>	Y		

## Structures in the Municipality of Portland

				CONDITION RATINGS	
<b>TOWN1:</b>	Portland	<b>TOWN2</b>	No town 2	<b>SUBSTRUCTURE CONDITION</b>	N      Not Applicable
<b>BRIDGE NO.:</b>	5238	<b>MAINT REGION</b>	Southern	<b>SUPERSTRUCTURE CONDITION</b>	N      Not Applicable
<b>LOCATION:</b>	AT INTER. PEASANT HIL	<b>YEAR BUILT</b>	1998	<b>DECK CONDITION</b>	N      Not Applicable
<b>BRIDGE NAME</b>	WASHINGTON AVE CUL	<b>SPAN MATERIAL</b>	7 Precast Concrete	<b>CHANNEL CONDITION:</b>	8      Very Good
<b>OWNER:</b>	1 State DOT	<b>SPAN TYPE:</b>	4 Culvert	<b>CULVERT CONDITION:</b>	8      Very Good
<b>MAINTAINER</b>	1 State DOT	<b>NUMBER OF MAIN SPANS:</b>	3	<b>APPROACH CONDITION:</b>	8      Very Good
<b>FEATURE ON:</b>	RTE 26 (WASHINGTON	<b>STRUCTURE LENGTH IN FEET</b>	33	<b>DATE OF INSPECTION:</b>	1/7/2009
<b>FEATURE UNDER</b>	FALL BROOK			<b>FEDERAL SUFFICIENCY RATING</b>	97.4
<b>ROAD INV NO:</b>	000000026X	<b>POSTING STATUS:</b>	1 Open		
<b>ROUTE NO:</b>	26	<b>POSTING TYPE:</b>	0 None needed		
<b>ROAD WIDTH</b>	0				
	<b>FEET</b>				
<b>CLASS:</b>	BRIDGE ON STATE HIGHWAY	<b>FEDERAL BRIDGE INDICATOR:</b>	Y		

## Structures in the Municipality of Portland

				<b>CONDITION RATINGS</b>	
<b>TOWN1:</b>	Portland	<b>TOWN2</b>	No town 2	<b>SUBSTRUCTURE CONDITION</b>	6 Satisfactory
<b>BRIDGE NO.:</b>	5616	<b>MAINT REGION</b>	Southern	<b>SUPERSTRUCTURE CONDITION</b>	7 Good
<b>LOCATION:</b>	.2 MI N 26	<b>YEAR BUILT</b>	1954	<b>DECK CONDITION</b>	6 Satisfactory
<b>BRIDGE NAME</b>	CNR CROSSING	<b>SPAN MATERIAL</b>	2 Concrete	<b>CHANNEL CONDITION:</b>	7 Good
<b>OWNER:</b>	1 State DOT	<b>SPAN TYPE:</b>	1 Girder	<b>CULVERT CONDITION:</b>	N Not Applicable
<b>MAINTAINER</b>	1 State DOT	<b>NUMBER OF MAIN SPANS:</b>	3	<b>APPROACH CONDITION:</b>	8 Very Good
<b>FEATURE ON:</b>	US1 & I295	<b>STRUCTURE LENGTH IN FEET</b>	160	<b>DATE OF INSPECTION:</b>	1/22/2009
<b>FEATURE UNDER</b>	CNRR	<b>FEDERAL SUFFICIENCY RATING</b>			
		96.6			
<b>ROAD INV NO:</b>	000000295X	<b>POSTING STATUS:</b>	1 Open		
<b>ROUTE NO:</b>	295	<b>POSTING TYPE:</b>	0 None needed		
<b>ROAD WIDTH</b>	98	<b>FEET</b>			
<b>CLASS:</b>	BRIDGE ON STATE HIGHWAY	<b>FEDERAL BRIDGE INDICATOR:</b>	Y		

## Structures in the Municipality of Portland

				<b>CONDITION RATINGS</b>		
<b>TOWN1:</b>	Portland	<b>TOWN2</b>	No town 2	<b>SUBSTRUCTURE CONDITION</b>	7	Good
<b>BRIDGE NO.:</b>	5617	<b>MAINT REGION</b>	Southern	<b>SUPERSTRUCTURE CONDITION</b>	7	Good
<b>LOCATION:</b>	.1 MI N 26	<b>YEAR BUILT</b>	1954	<b>DECK CONDITION</b>	7	Good
<b>BRIDGE NAME</b>	SHERWOOD ST.	<b>SPAN MATERIAL</b>	2 Concrete	<b>CHANNEL CONDITION:</b>	8	Very Good
<b>OWNER:</b>	1 State DOT	<b>SPAN TYPE:</b>	1 Girder	<b>CULVERT CONDITION:</b>	N	Not Applicable
<b>MAINTAINER</b>	1 State DOT	<b>NUMBER OF MAIN SPANS:</b>	1	<b>APPROACH CONDITION:</b>	6	Satisfactory
<b>FEATURE ON:</b>	US1 & I295	<b>STRUCTURE LENGTH IN FEET</b>	44	<b>DATE OF INSPECTION:</b>	1/22/2009	
<b>FEATURE UNDER</b>	SHERWOOD STREET			<b>FEDERAL SUFFICIENCY RATING</b>	94.7	
<b>ROAD INV NO:</b>	000000295X	<b>POSTING STATUS:</b>	1 Open			
<b>ROUTE NO:</b>	295	<b>POSTING TYPE:</b>	0 None needed			
<b>ROAD WIDTH</b>	100	<b>FEET</b>				
<b>CLASS:</b>	BRIDGE ON STATE HIGHWAY			<b>FEDERAL BRIDGE INDICATOR:</b>	Y	

## Structures in the Municipality of Portland

				<b>CONDITION RATINGS</b>	
<b>TOWN1:</b>	Portland	<b>TOWN2</b>	No town 2	<b>SUBSTRUCTURE CONDITION</b>	6 Satisfactory
<b>BRIDGE NO.:</b>	5618	<b>MAINT REGION</b>	Southern	<b>SUPERSTRUCTURE CONDITION</b>	7 Good
<b>LOCATION:</b>	.2MI N 26	<b>YEAR BUILT</b>	1954	<b>DECK CONDITION</b>	7 Good
<b>BRIDGE NAME</b>	KENSINGTON STREET	<b>SPAN MATERIAL</b>	2 Concrete	<b>CHANNEL CONDITION:</b>	6 Satisfactory
<b>OWNER:</b>	1 State DOT	<b>SPAN TYPE:</b>	1 Girder	<b>CULVERT CONDITION:</b>	N Not Applicable
<b>MAINTAINER</b>	1 State DOT	<b>NUMBER OF MAIN SPANS:</b>	1	<b>APPROACH CONDITION:</b>	6 Satisfactory
<b>FEATURE ON:</b>	US 1 & I295	<b>STRUCTURE LENGTH IN FEET</b>	53	<b>DATE OF INSPECTION:</b>	1/22/2009
<b>FEATURE UNDER</b>	KENSINGTON STREET	<b>FEDERAL SUFFICIENCY RATING</b>			
		94.5			
<b>ROAD INV NO:</b>	000000295X	<b>POSTING STATUS:</b>	3 Posted		
<b>ROUTE NO:</b>	295	<b>POSTING TYPE:</b>	3 Underclearance Limit		
<b>ROAD WIDTH</b>	100				
	<b>FEET</b>				
<b>CLASS:</b>	BRIDGE ON STATE HIGHWAY	<b>FEDERAL BRIDGE INDICATOR:</b>	Y		

## Structures in the Municipality of Portland

				CONDITION RATINGS	
<b>TOWN1:</b>	Portland	<b>TOWN2</b>	No town 2	<b>SUBSTRUCTURE CONDITION</b>	6 Satisfactory
<b>BRIDGE NO.:</b>	5915	<b>MAINT REGION</b>	Southern	<b>SUPERSTRUCTURE CONDITION</b>	7 Good
<b>LOCATION:</b>	0.2 MI N OF INT MARG.	<b>YEAR BUILT</b>	1960	<b>DECK CONDITION</b>	6 Satisfactory
<b>BRIDGE NAME</b>	OVERPASS 2	<b>SPAN MATERIAL</b>	1 Steel	<b>CHANNEL CONDITION:</b>	6 Satisfactory
<b>OWNER:</b>	1 State DOT	<b>SPAN TYPE:</b>	1 Girder	<b>CULVERT CONDITION:</b>	N Not Applicable
<b>MAINTAINER</b>	1 State DOT	<b>NUMBER OF MAIN SPANS:</b>	3	<b>APPROACH CONDITION:</b>	6 Satisfactory
<b>FEATURE ON:</b>	RTE 26 NB(9WASH.AV	<b>STRUCTURE LENGTH IN FEET</b>	181	<b>DATE OF INSPECTION:</b>	1/22/2009
<b>FEATURE UNDER</b>	EAST COMMERCIAL ST			<b>FEDERAL SUFFICIENCY RATING</b>	97.4
<b>ROAD INV NO:</b>	000000026X	<b>POSTING STATUS:</b>	1 Open		
<b>ROUTE NO:</b>	26	<b>POSTING TYPE:</b>	0 None needed		
<b>ROAD WIDTH</b>	33				
	<b>FEET</b>				
<b>CLASS:</b>	BRIDGE ON STATE HIGHWAY	<b>FEDERAL BRIDGE INDICATOR:</b>	Y		

## Structures in the Municipality of South Portland

				CONDITION RATINGS	
<b>TOWN1:</b>	South Portland	<b>TOWN2</b>	Portland	<b>SUBSTRUCTURE CONDITION</b>	6 Satisfactory
<b>BRIDGE NO.:</b>	6281	<b>MAINT REGION</b>	Southern	<b>SUPERSTRUCTURE CONDITION</b>	6 Satisfactory
<b>LOCATION:</b>	TOWNLINE	<b>YEAR BUILT</b>	1973	<b>DECK CONDITION</b>	6 Satisfactory
<b>BRIDGE NAME</b>	I 295 / FORE RIVER	<b>SPAN MATERIAL</b>	1 Steel	<b>CHANNEL CONDITION:</b>	6 Satisfactory
<b>OWNER:</b>	1 State DOT	<b>SPAN TYPE:</b>	1 Girder	<b>CULVERT CONDITION:</b>	N Not Applicable
<b>MAINTAINER</b>	1 State DOT	<b>NUMBER OF MAIN SPANS:</b>	5	<b>APPROACH CONDITION:</b>	6 Satisfactory
<b>FEATURE ON:</b>	INTERSTATE 295	<b>STRUCTURE LENGTH IN FEET</b>	607	<b>DATE OF INSPECTION:</b>	1/28/2010
<b>FEATURE UNDER</b>	FORE RIVER			<b>FEDERAL SUFFICIENCY RATING</b>	95.5
<b>ROAD INV NO:</b>	000000295X	<b>POSTING STATUS:</b>	1 Open		
<b>ROUTE NO:</b>	295	<b>POSTING TYPE:</b>	0 None needed		
<b>ROAD WIDTH</b>	84				
	<b>FEET</b>				
<b>CLASS:</b>	BRIDGE ON STATE HIGHWAY	<b>FEDERAL BRIDGE INDICATOR:</b>	Y		

## Structures in the Municipality of South Portland

				CONDITION RATINGS	
<b>TOWN1:</b>	South Portland	<b>TOWN2</b>	Portland	<b>SUBSTRUCTURE CONDITION</b>	8      Very Good
<b>BRIDGE NO.:</b>	5900	<b>MAINT REGION</b>	Southern	<b>SUPERSTRUCTURE CONDITION</b>	9      Excellent
<b>LOCATION:</b>	PORTLAND - S PORTLA	<b>YEAR BUILT</b>	1998	<b>DECK CONDITION</b>	8      Very Good
<b>BRIDGE NAME</b>	CASCO BAY	<b>SPAN MATERIAL</b>	1 Steel	<b>CHANNEL CONDITION:</b>	7      Good
<b>OWNER:</b>	1 State DOT	<b>SPAN TYPE:</b>	2 Girder - floor beam	<b>CULVERT CONDITION:</b>	N      Not Applicable
<b>MAINTAINER</b>	1 State DOT	<b>NUMBER OF MAIN SPANS:</b>	1	<b>APPROACH CONDITION:</b>	7      Good
<b>FEATURE ON:</b>	ROUTE 77	<b>STRUCTURE LENGTH IN FEET</b>	4748	<b>DATE OF INSPECTION:</b>	2/4/2010
<b>FEATURE UNDER</b>	FORE RIVER			<b>FEDERAL SUFFICIENCY RATING</b>	89.9
<b>ROAD INV NO:</b>	000000077W	<b>POSTING STATUS:</b>	1 Open		
<b>ROUTE NO:</b>	77	<b>POSTING TYPE:</b>	0 None needed		
<b>ROAD WIDTH</b>	72				
	<b>FEET</b>				
<b>CLASS:</b>	BRIDGE ON STATE HIGHWAY	<b>FEDERAL BRIDGE INDICATOR:</b>	Y		

## Structures in the Municipality of South Portland

				CONDITION RATINGS	
<b>TOWN1:</b>	South Portland	<b>TOWN2</b>	Portland	<b>SUBSTRUCTURE CONDITION</b>	4 <span style="margin-left: 20px; border: 1px solid black; padding: 2px;">Poor</span>
<b>BRIDGE NO.:</b>	3945	<b>MAINT REGION</b>	Southern	<b>SUPERSTRUCTURE CONDITION</b>	5 <span style="margin-left: 20px; border: 1px solid black; padding: 2px;">Fair</span>
<b>LOCATION:</b>	TOWNLINE	<b>YEAR BUILT</b>	1954	<b>DECK CONDITION</b>	4 <span style="margin-left: 20px; border: 1px solid black; padding: 2px;">Poor</span>
<b>BRIDGE NAME</b>	VETERANS MEMORIAL	<b>SPAN MATERIAL</b>	1 Steel	<b>CHANNEL CONDITION:</b>	5 <span style="margin-left: 20px; border: 1px solid black; padding: 2px;">Fair</span>
<b>OWNER:</b>	1 State DOT	<b>SPAN TYPE:</b>	2 Girder - floor beam	<b>CULVERT CONDITION:</b>	N <span style="margin-left: 20px; border: 1px solid black; padding: 2px;">Not Applicable</span>
<b>MAINTAINER</b>	1 State DOT	<b>NUMBER OF MAIN SPANS:</b>	10	<b>APPROACH CONDITION:</b>	7 <span style="margin-left: 20px; border: 1px solid black; padding: 2px;">Good</span>
<b>FEATURE ON:</b>	ROUTE US 1	<b>STRUCTURE LENGTH IN FEET</b>	2150	<b>DATE OF INSPECTION:</b>	2/4/2010
<b>FEATURE UNDER</b>	FORE RIVER & P T RR			<b>FEDERAL SUFFICIENCY RATING</b>	47.7
<b>ROAD INV NO:</b>	0003201019	<b>POSTING STATUS:</b>	1 Open		
<b>ROUTE NO:</b>	0	<b>POSTING TYPE:</b>	0 None needed		
<b>ROAD WIDTH</b>	52 <b>FEET</b>				
<b>CLASS:</b>	BRIDGE ON STATE HIGHWAY	<b>FEDERAL BRIDGE INDICATOR:</b>	Y		